

SVP-98-116

March 27, 1998

U.S. Nuclear Regulatory Commission Washington, DC 20555

Attn:

Document Control Desk

Reference:

Quad Cities Nuclear Power Station

Docket Number 50-254, DPR-29, Unit One Docket Number 50-265, DPR-30, Unit Two

Enclosed is Licensee Event Report (LER) 97-030, Revision 1, for Quad Cities Nuclear Power Station. This event dealt with Instrument Line Excess Flow Valves Testing performed at less than nominal reactor pressure due to apparent inadequate procedures.

This report is being submitted to provide additional information following completion of the root cause analysis referenced in LER 97-030, Revision 0.

The following commitments are being made by this letter.

- The instrument maintenance procedure (QCIS 0200-22) will be revised to perform just-intime training on the acceptance criteria (0.3 gpm at 1000 psig differential pressure) each time prior to performing this test. Due date: 061598.
- The IST Coordinator to review the IST Program Plan and QCIS 0200-22 and verify
 that the procedure adequately implements the ASME Code requirements of the
 Program Plan and that the implementation of the applicable ASME Code sections are
 consistent with other ComEd BWRs. Due date: 060198.
- 3. As a part of the IST Program assessment and revision effort that is currently ongoing, one objective will be to establish a methodology (e.g., software or checklist) for ensuring adequate documentation that the Program implementation meets the as committed ASME and/or Operations & Maintenance (OMa) part 10 requirements, and thus aid in the periodic verification of IST Program implementation. Due date: 073198.

Len

9804080127 980327 PDR ADOCK 05000254 S PDR

- IST Coordinator to incorporate this root cause investigation report and the associated LER in the IST Coordinator's position qualification card as required reading. Due date: 063098.
- Instrument Maintenance Department to retest the Unit 2 excess flow check valves at nominal reactor pressure corresponding to 100 percent rated power prior to Unit startup.
- Instrument Maintenance Department to retest the Unit 1 Excess flow check valves at nominal reactor pressure corresponding to 100 percent rated power prior to Unit startup.

If there are any questions or comments concerning this letter, please refer them to Charles Peterson, Regulatory Affairs Manager at 309-654-2241, ext. 3609.

Respectfully,

David A Sager Site Vice President Quad Cities Station

DAS/CP/lmc

cc: A. B. Beach, Regional Administrator, Region III

R. M. Pulsifer, Project Manager, NRR

C. G. Miller, Senior Resident Inspector, Quad Cities

W. D. Leech, MidAmerican Energy Company

D. C. Tubbs, MidAmerican Energy Company

M. E. Wagner, Licensing, ComEd

F. A. Spangenberg, Regulatory Affairs Manager, Dresden

INPO Records Center