AUG 2 4 1989

Docket No. 50-293

Boston Edison Company
ATTN: Mr. Ralph G. Bird
Senior Vice President - Nuclear
Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, Massachusetts 02360

Gentlemen:

Subject: 10 CFR 50.54 QUALITY ASSURANCE PROGRAM DESCRIPTION CHANGE REVIEW

Reference:

Letter BECo 89-091 dated June 30, 1989, Ralph G. Bird to U. S. Nuclear Regulatory Commission, Subject: Annual Report of Changes to the Boston Edison Quality Assurance Program Description

We have received the referenced letter transmitting the Summary of QA Program Description Changes (1989) of the Boston Edison Quality Assurance Program Description. The Region I staff has reviewed these submittals and found they do not reduce your previous commitments to quality assurance and, therefore, are acceptable.

The effectiveness of your Quality Assurance Program and procedure implementation will continue to be the subject of routine regional inspections.

If you have any questions concerning the above, please call R. W. Winters on (215) 337-5244.

Sincerely,

Original Signed By: Clifford J. Anderson

Jacque P. Durr, Chief Engineering Branch Division of Reactor Safety

OFFICIAL RECORD COPY

50-293 QA - 0001.0.0 08/24/89

IE: O

```
cc w/encl:
```

K. Highfill, Station Director

R. Anderson, Plant Manager

J. Keyes, Licensing Division Manager

E. Robinson, Nuclear Information Manager

R. Swanson, Nuclear Engineering Department Manager

The Honorable Edward J. Markey The Honorable Edward P. Kirby

The Honorable Peter V. Forman

The Honorable Lawrence R. Alexander

The Honorable Nicholas J. Costello

B. McIntyre, Chairman, Department of Public Utilities

Chairman, Plymouth Board of Selectmen

Chairman, Duxbury Board of Selectmen

Plymouth Civil Defense Director

P. Agnes, Assistant Secretary of Public Safety, Commonwealth of Massachusetts

S. Pollard, Massachusetts Secretary of Energy Resources

R. Shimshak, MASSPIRG

Public Document Room (PDR)

Local Public Document Room (LPDR)

Nuclear Safety Information Center (NSIC)

NRC Resident Inspector

Commonwealth of Massachusetts (2)

bcc w/encl:

Region I Docket Room (with concurrences)

-Management Assistant, DRMA (w/o encl)

W. Russell, RA

J. Dyer, EDO

R. Wessman, NRR

D. McDonald, NRR

S. Collins, DRP

J. Wiggins, DRP

R. Blough, DRP

J. Lyash, DRP

M. Kohl, DRP

C. Warren, SRI - Filgrim (with concurrences)

PAO (21) Salp Reports and All Inspection Reports

RIMBRS Winters/rw 8/24/89 RI:DRS Durr 8/17/89

OFFICIAL RECORD COPY

50-293 QA - 0002.0.0 08/24/89 =

BOSTON EDISON

Pilgrim Nuclear Power Station Rocky Hill Road Plymouth, Massachusetts 02360 10CFR50.54(a) Pimaile 7/5/89 Rec'd Region 7/7/89 Rec'd Rigion 7/7/89

Ralph G. Bird
Senior Vice President — Nuclear
U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

BECo 89-091

June 30, 1989

License DPR-35 Docket 50-293

ANNUAL REPORT OF CHANGES TO THE BOSTON EDISON QUALITY ASSURANCE PROGRAM DESCRIPTION

As required by 10CFR50.54(a), Boston Edison submits the annual summary of changes made to the Boston Edison Quality Assurance Program Description as listed in the Boston Edison Quality Assurance Manual (BEQAM), Volume II.

We evaluated each change, summarized in enclosure (A), to determine if any requirements contained in the previously NRC-approved QA Program Description were deleted or made less stringent. We concluded there were no reductions of commitments. 10CFR50, Appendix B, Criterion II requirements were used to conclude the revised program continues to satisfy the criteria of Appendix B.

GGW/amm/3398

Enclosure: (A) Summary of the Boston Edison QA Program Description Changes (1988-1989)

Mr. D. McDonald, Project Manager
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation
Mail Stop: 14Dl
U. S. Nuclear Regulatory Commission
1 White Flint North
11555 Rockville Pike
Rockville, MD 02852

U. S. Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406

Senior NRC Resident Inspector Pilgrim Nuclear Power Station

890713\$\$25 4PP

SUMMARY OF THE BOSTON EDISON QA PROGRAM DESCRIPTION CHANGES (1988-1989)

QA PROGRAM CHANGE #II-213 EVALUATION #88-28

This change modifies Section 18 of BEQAM II as follows:

To clarify and strengthen the requirements related to Supplier Finding Reports.

The revised program incorporating this change continues to satisfy the criteria of 10CFR50, Appendix B, and the Safety Analysis Report Quality Assurance Program description commitments previously accepted by the NRC.

QA PROGRAM CHANGE #II-214 EVALUATION #88-29

Void; no change was made to the BEQAM.

QA PROGRAM CHANGE #II-215 EVALUATION #88-30

Void; no change was made to the BEOAM.

QA PROGRAM CHANGE #II-216 EVALUATION #88-31

This change modifies Section 18 of BEQAM II as follows:

To clarify the requirements relative to the escalation time limits for Deficiency Reports without proper resolution.

The revised program incorporating this change continues to satisfy the criteria of 10CFR50, Appendix B, and the Safety Analysis Report Quality Assurance Program description commitments previously accepted by the NRC.

QA PROGRAM CHANGE #II-217 EVALUATION #88-32

This change modifies Section 13 of BEQAM II as follows:

To reflect existing practice, using Stores/Claims to document discrepancies found during receipt inspection.

The revised program incorporating this change continues to satisfy the criteria of 10CFR50, Appendix B, and the Safety Analysis Report Quality Assurance Program description commitments previously accepted by the NRC.

QA PROGRAM CHANGE #II-218 EVALUATION #88-33

This change modifies Section 4 of BEQAM II as follows:

To add explanatory detail about the Commercial Quality Item (CQI) process. Also, to provide a way to upgrade a non-Q item to Q if it meets the tests required for a CQI.

To change the title of Vice President Nuclear Engineering to Director of Nuclear Engineering.

The revised program incorporating this change continues to satisfy the criteria of 10CFR50, Appendix B, and the Safety Analysis Report Quality Assurance Program description commitments previously accepted by the NRC.

QA PROGRAM CHANGE #II-219 EVALUATION #88-34

This change modifies Section 7 of BEQAM II as follows:

For consistency with the changes made to Section 4 by QA Program Change Request II-218.

Also, to explicitly address the use of the Material Receiving Inspection Report (MRIR), the QA Material Conformance Tag, and the MRIR Number.

The revised program incorporating this change continues to satisfy the criteria of 10CFR50, Appendix B, and the Safety Analysis Report Quality Assurance Program description commitments previously accepted by the NRC.

QA PROGRAM CHANGE #II-220 EVALUATION #88-35

This change modifies Section 8 of BEQAM II as follows:

To explicitly address the use of the Material Receiving Inspection Report (MRIR), the QA Material Conformance Tag, and the MRIR Number, consistent with QA Program Change Request II-219.

The revised program incorporating this change continues to satisfy the criteria of 10CFR50, Appendix B, and the Safety Analysis Report Quality Assurance Program description commitments previously accepted by the NRC.

QA PROGRAM CHANGE #II-221 EVALUATION #89-01

This change modifies Section 10 of BEQAM II as follows:

To remove the requirement for Quality Control to maintain copies of Installation Inspection Reports in Quality Assurance Department files since they are already captured as BECo QA Records in accordance with ANSI N45.2.9, and there is no need for redundant official files.

The revised program incorporating this change continues to satisfy the criteria of 10CFR50, Appendix B, and the Safety Analysis Report Quality Assurance Program description commitments previously accepted by the NRC.