



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAY 12 1989

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. P. M. Byron, E. R. Schweibinz, R. K. Walton, and D. C. Kosloff of this office on March 1 through April 23, 1989, of activities at Davis-Besse Nuclear Power Station, authorized by Facility Operating License No. NPF-3, and to the discussion of our findings with Mr. L. Storz at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in Paragraphs 5.a. and 5.b. of the enclosed report. However, these were identified by you and meet the criteria of 10 CFR 2, Appendix C, Section V.G and therefore, a Notice of Violation will not be issued.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. C. Knop
R. C. Knop, Chief
Reactor Projects Branch 3

Enclosures:

1. Inspection Report
No. 50-346/89011(DRP)
2. Licensee Handout at 3/13/89
Enforcement Conference

See Attached Distribution

8905250173 890512
PDR ADOCK 05000346
Q PDC

LEO1
11

Distribution

cc w/enclosure:

L. Storz, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Harold W. Kohn, Ohio EPA

James W. Harris, State of Ohio

Roger Suppes, Ohio

Department of Health

State of Ohio, Public

Utilities Commission