Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President

Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

## Gentlemen:

On July 21, 1989, you submitted the 10 CFR 50.71(e) annual update of your UFSAR to the Document Control Desk in accordance with 10 CFR 50.4. However, a copy of the update report, or replacement pages, must also be submitted to the appropriate regional office per 50.4(b)(6) Although the transmittal letter was received by the regional office, 10 CFR 50.54(a)(3) required update information was not received, including all pages affected by that change, the reason for the change, and the basis for concluding that the revised program continues to satisfy Appendix B. Based on a conversation between Mr. Joe Sturdavant of your staff and Mr. T. Vandel of my staff, on September 13, 1989, we understand that Mr. Sturdavant will provide a review package to the region by express mail.

We plan to review the updated Quality Assurance Program Description, Section 17.2, however, our review will require more than sixty days to complete due to the lack of available information. You will be notified of the results.

You are advised that adherence to the 10 CFR Part 50 regulations is expected and that further lack of responsiveness may result in enforcement action. Please contact Mr. Monte Phillips of my staff (312/790-5530) with any questions you have regarding this matter.

Sincerely,

Thomas M. Burdick for

Geoffrey C. Wright, Chief Operations Branch

cc: L. Storz, Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
James W. Harris, State of Ohio
Roger Suppes, Ohio
Department of Health
A. Grandjean, State of Ohio,
Public Utilities Commission

F. C. Hawkins, NRR

BHI GE

RIII

RM1 Wright

10

IEO1

8910020226 890925 FDR ADDCK 05000346