



October 27, 2022

ULNRC-06775

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555-0001

10 CFR 50.4

Ladies and Gentlemen:

**DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
UNION ELECTRIC CO.
RENEWED FACILITY OPERATING LICENSE NPF-30
SPECIAL REPORT 2022-03
NON-FUNCTIONALITY OF LOOSE-PART DETECTION SYSTEM
CHANNEL FOR GREATER THAN 30 DAYS**

Enclosed is a special report addressing the non-functionality of a Loose-Parts Detection System channel at Callaway Plant.

No new commitments are identified in this correspondence, and none of the material in this report is considered proprietary by Union Electric Company (Ameren Missouri).

If there are any questions, please contact Mr. Thomas Elwood, Supervising Engineer, Regulatory Affairs and Licensing at 314-225-1905.

Sincerely,

Todd Witt,
Manager, Regulatory Affairs

Enclosure

cc: Mr. Scott A. Morris
Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV
1600 East Lamar Boulevard
Arlington, TX 76011-4511

Senior Resident Inspector
Callaway Resident Office
U.S. Nuclear Regulatory Commission
8201 NRC Road
Steedman, MO 65077

Mr. M. Chawla
Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop O8B1A
Washington, DC 20555-0001

Index and send hardcopy to QA File A160.0761

Hardcopy:

Certrec Corporation
6500 West Freeway, Suite 400
Fort Worth, TX 76116
(Certrec receives ALL attachments as long as they are non-safeguards and may be publicly disclosed.)

Electronic distribution for the following can be made via Responses and Reports ULNRC Distribution:

F. M. Diya
B. L. Cox
F. J. Bianco
D. Farnsworth
B.L. Jungmann
T. A. Witt
T. B. Elwood
M.W. Dancer
NSRB Secretary
STARS Regulatory Affairs
Mr. Jay Silberg (Pillsbury Winthrop Shaw Pittman LLP)
Missouri Public Service Commission