

Progress Energy Florida
Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report

Hourly PMP Rainfall Distribution for the Inglis Dam

FIGURE 2.4.3-206 Rev 0