

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

January 3, 2000

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555-0001

Serial No.: 99-618
NLOS/MM
Docket No.: 50-339
License No.: NPF-7

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION UNIT 2
INSERVICE INSPECTION SUMMARY REPORT
FOR THE FALL 1999 REFUELING OUTAGE

As set forth in the provisions of ASME Section XI, Paragraph IWA-6230, enclosed is the Inservice Inspection Summary Report for North Anna Power Station Unit 2 for the Fall 1999 refueling outage. This report provides a summary of the examinations performed during the outage for the third inservice inspection interval. In addition, the report summarizes the inspection activities associated with 10 CFR 50.55a(b)(ix)(E) and 10 CFR 50.55a(b)(x)(A).

In accordance with IWA-6220 of ASME Section XI, Attachment 1 includes a Form NIS-1, "Owner's Report for Inservice Inspections," an examination summary, and abstracts of examinations performed. Attachment 2 includes Forms NIS-2, "Owner's Report for Repairs or Replacements."

The entire report will be maintained on file at the corporate office. If you have any questions or require additional information, please contact us.

Very truly yours,



L. N. Hartz
Vice President - Nuclear Engineering and Services

Attachments

A047

cc: U. S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth St., SW, Suite 23 T85
Atlanta, GA 30303-3415

Mr. M. J. Morgan
NRC Senior Resident Inspector
North Anna Power Station

Mr. M. Grace
Authorized Nuclear Inspector
North Anna Power Station

Mr. J. A. Reasor
Old Dominion Electric Cooperative
Innsbrook Corporate Center
4210 Dominion Blvd.
Glen Allen, Virginia 23260