Mr. L. W. Myers Senior Vice President FirstEnergy Nuclear Operating Company Post Office Box 4 Shippingport, PA 15077

SUBJECT: COMPLETION OF LICENSING ACTION FOR GENERIC LETTER 98-04,

"POTENTIAL FOR DEGRADATION OF THE EMERGENCY CORE COOLING SYSTEM AND THE CONTAINMENT SPRAY SYSTEM AFTER A LOSS-OF-COOLANT ACCIDENT BECAUSE OF CONSTRUCTION AND PROTECTIVE COATING DEFICIENCIES AND FOREIGN MATERIAL IN CONTAINMENT," BEAVER VALLEY POWER STATION, UNIT NOS. 1 AND 2 (TAC NOS. MA4017)

AND MA4018)

Dear Mr. Myers:

On July 14, 1998, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 98-04, "Potential for Degradation of the Emergency Core Cooling System and the Containment Spray System After a Loss-of-Coolant Accident Because of Construction and Protective Coating Deficiencies and Foreign Material in Containment," to all holders of operating licenses or construction permits. The NRC issued GL 98-04 to determine the status of containment coating programs.

In GL 98-04, the NRC staff specifically requested that the licensees provide information outlined below for each of their facilities.

- (1) A summary description of the plant-specific program or programs implemented to ensure that Service Level 1 protective coatings used inside the containment are procured, applied, and maintained in compliance with applicable regulatory requirements and the plant-specific licensing basis for the facility. Include a discussion of how the plant-specific program meets the applicable criteria of 10 CFR Part 50, Appendix B, as well as information regarding any applicable standards, plant-specific procedures, or other guidance used for (a) controlling the procurement of coatings and paints used at the facility; (b) the qualification testing of protective coatings; and (c) surface preparation, application, surveillance, and maintenance activities for protective coatings. Maintenance activities refer to rework of degraded coatings, removing degraded coatings to sound coatings, correctly preparing the surfaces, applying new coating, and verifying the quality of coatings.
- (2) Information demonstrating compliance with item (i) or item (ii).
 - (i) For plants with licensing-basis requirements for tracking the amount of unqualified coatings inside the containment and for assessing the impact of potential coating debris on the operation of safety-related systems, structures, and components (SSCs) during a postulated design basis loss-of-coolant accident (DB LOCA), the following information shall be provided to demonstrate compliance:

- (a) The date and findings of the last assessment of coatings and the planned date of the next assessment of coatings.
- (b) The limit for the amount of unqualified protective coatings allowed in the containment and how this limit is determined. Discuss any conservatism in the method used to determine this limit.
- (c) If a commercial-grade dedication program is being used at your facility for dedicating commercial-grade coatings for Service Level 1 applications inside the containment, discuss how the program adequately qualifies a coating for Service Level 1. Identify what standards or other guidance are currently being used to dedicate containment coatings at your facility.
- (ii) For plants without the above licensing-basis requirements, information shall be provided to demonstrate compliance with the requirements of 10 CFR 50.46b(5), "Long-term cooling" and the functional capability of the safety-related containment spray system (CSS) as set forth in your licensing basis. If a licensee can demonstrate this compliance without quantifying the amount of unqualified coatings, this is acceptable. The following information shall be provided:

If a commercial-grade dedication program is not being used at your facility for qualifying and dedicating commercial-grade coatings for Service Level 1 applications, provide the regulatory and safety basis for not controlling these coatings in accordance with such a program. Additionally, explain why the facility's licensing basis does not require such a program.

In response to GL 98-04, you provided a letter dated November 11, 1998, for the Beaver Valley Power Station, Unit Nos. 1 and 2. This submittal provided the information requested by GL 98-04. Clarification was provided during a phone call that took place on May 20, 1999. The staff has reviewed your response and has concluded that all requested information has been provided; therefore, we consider GL 98-04 to be closed for your facility. We thank you for your prompt and complete response.

If you have any questions regarding this matter, please contact me at (301) 415-1427.

Sincerely,

/RA/

Daniel S. Collins, Project Manager, Section 1 Project Directorate I Division of Licensing Project Management Office of Nuclear Reactor Regulation

Docket Nos. 50-334 and 50-412

cc: See next page

- The date and findings of the last assessment of coatings and the planned date (a) of the next assessment of coatings.
- The limit for the amount of unqualified protective coatings allowed in the (b) containment and how this limit is determined. Discuss any conservatism in the method used to determine this limit.
- If a commercial-grade dedication program is being used at your facility for dedicating commercial-grade coatings for Service Level 1 applications inside the containment, discuss how the program adequately qualifies a coating for Service Level 1. Identify what standards or other guidance are currently being used to dedicate containment coatings at your facility.
- For plants without the above licensing-basis requirements, information shall be provided to demonstrate compliance with the requirements of 10 CFR 50.46b(5), "Long-term cooling" and the functional capability of the safety-related containment spray system (CSS) as set forth in your licensing basis. If a licensee can demonstrate this compliance without quantifying the amount of unqualified coatings, this is acceptable. The following information shall be provided:

If a commercial-grade dedication program is not being used at your facility for qualifying and dedicating commercial-grade coatings for Service Level 1 applications, provide the regulatory and safety basis for not controlling these coatings in accordance with such a program. Additionally, explain why the facility's licensing basis does not require such a program.

In response to GL 98-04, you provided a letter dated November 11, 1998, for the Beaver Valley Power Station, Unit Nos. 1 and 2. This submittal provided the information requested by GL 98-04. Clarification was provided during a phone call that took place on May 20, 1999. The staff has reviewed your response and has concluded that all requested information has been provided; therefore, we consider GL 98-04 to be closed for your facility. We thank you for your prompt and complete response.

If you have any questions regarding this matter, please contact me at (301) 415-1427.

Sincerely,

/RA/

Daniel S. Collins, Project Manager, Section 1

Project Directorate I

Division of Licensing Project Management

Office of Nuclear Reactor Regulation

Docket Nos. 50-334 and 50-412

cc: See next page DISTRIBUTION

File Center MGamberoni RPulsifer OGC

PUBLIC MOB'rien CLauron **ACRS**

PDI-1 Reading **DCollins JDavis**

EAdensam (EGA1) **ESullivan** PEselgroth, RGN 1

OFFICE	PDI-1/PM	PDI-2/LA	EMCB/SC	PDI-1/SC
NAME	DCollins	MO'Brien	ESullivan	MGamberoni
DATE	12/22/99	12/22/99	12/22/99	1/12/00

OFFICIAL RECORD COPY

DOCUMENT NAME: C:\ltra4017.wpd

Beaver Valley Power Station, Units 1 and 2

Jay E. Silberg, Esquire Shaw, Pittman, Potts & Trowbridge 2300 N Street, NW. Washington, DC 20037

First Energy Nuclear Operating Company Licensing Section Mark S. Ackerman, Manager (2 Copies) Beaver Valley Power Station PO Box 4, BV-A Shippingport, PA 15077

Commissioner Roy M. Smith West Virginia Department of Labor Building 3, Room 319 Capitol Complex Charleston, WV 25305

Director, Utilities Department Public Utilities Commission 180 East Broad Street Columbus, OH 43266-0573

Director, Pennsylvania Emergency Management Agency Post Office Box 3321 Harrisburg, PA 17105-3321

Ohio EPA-DERR ATTN: Zack A. Clayton Post Office Box 1049 Columbus, OH 43266-0149

Dr. Judith Johnsrud National Energy Committee Sierra Club 433 Orlando Avenue State College, PA 16803

First Energy Nuclear Operating Company Beaver Valley Power Station J. J. Maracek P. O. Box 4, BV-A Shippingport, PA 15077 First Energy Nuclear Operating Company Beaver Valley Power Station PO Box 4 Shippingport, PA 15077 ATTN: Kevin L. Ostrowski, Plant General Manager (BV-SOSB-7)

Bureau of Radiation Protection Pennsylvania Department of Environmental Protection ATTN: Michael P. Murphy Post Office Box 2063 Harrisburg, PA 17120

Mayor of the Borough of Shippingport Post Office Box 3 Shippingport, PA 15077

Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Resident Inspector U.S. Nuclear Regulatory Commission Post Office Box 298 Shippingport, PA 15077

First Energy Nuclear Operating Company Beaver Valley Power Station PO Box 4 Shippingport, PA 15077 ATTN: M. P. Pearson, Director Plant Services (BV-NCD-3)

Mr. J. A. Hultz, Manager Projects & Support Services First Energy 76 South Main Street Akron, OH 44308