

Mr. Oliver D. Kingsley
 President, Nuclear Generation Group
 Commonwealth Edison Company
 ATTN: Regulatory Services
 Executive Towers West III
 1400 Opus Place, Suite 500
 Downers Grove, IL 60515

SUBJECT: BRAIDWOOD INSPECTION REPORT 50-456/99018(DRP); 50-457/99018(DRP)

Dear Mr. Kingsley:

On December 20, 1999, the NRC completed an inspection at your Braidwood Units 1 and 2 reactor facilities. The enclosed report presents the results of that inspection.

During the 6-week period covered by this inspection, your conduct of activities was generally characterized by safety-conscious operations, sound engineering and maintenance practices, and careful radiological work controls.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Sincerely,

/s/ M. Jordan

Michael J. Jordan, Chief
 Reactor Projects Branch 3

Docket Nos. 50-456; 50-457
 License Nos. NPF-72; NPF-77

Enclosure: Inspection Report 50-456/99018(DRP);
 50-457/99018(DRP)

See Attached Distribution

DOCUMENT NAME: G:/BRAI/BRA99018.DRP

To receive a copy of this document, indicate in the box "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure
 "N" = No copy

OFFICE	RIII	<input checked="" type="checkbox"/> E	RIII	<input checked="" type="checkbox"/> N	RIII	<input checked="" type="checkbox"/> N	RIII	<input checked="" type="checkbox"/> E
NAME	Tongue/mt/dp <i>atmg</i>		Shear <i>SDJ</i> (Sec P1.1)		Gardner <i>N</i> (Sec M2.1; M8.1)		Jordan <i>mjl</i>	
DATE	01/06/00		01/16/00		01/16/00		01/17/00	

OFFICIAL RECORD COPY

PDR A Doc 10

O. Kingsley

-2-

cc w/encl: D. Helwig, Senior Vice President, Nuclear Services
C. Crane, Senior Vice President, Nuclear Operations
H. Stanley, Vice President, Nuclear Operations
R. Krich, Vice President, Regulatory Services
DCD - Licensing
T. Tulon, Site Vice President
K. Schwartz, Station Manager
T. Simpkin, Regulatory Assurance Supervisor
M. Aguilar, Assistant Attorney General
State Liaison Officer
Chairman, Illinois Commerce Commission

Distribution:

RPC (E-Mail)

GFD (Project Mgr.) (E-Mail)

J. Caldwell, RIII w/encl

B. Clayton, RIII w/encl

SRI Braidwood w/encl

DRP w/encl

DRS w/encl

RIII PRR w/encl

PUBLIC IE-01 w/encl

Docket File w/encl

GREENS

IEO (E-Mail)

DOCDESK (E-Mail)



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
801 WARRENVILLE ROAD
LISLE, ILLINOIS 60532-4351

January 07, 2000

Mr. Oliver D. Kingsley
President, Nuclear Generation Group
Commonwealth Edison Company
ATTN: Regulatory Services
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT: BRAIDWOOD INSPECTION REPORT 50-456/99018(DRP); 50-457/99018(DRP)

Dear Mr. Kingsley:

On December 20, 1999, the NRC completed an inspection at your Braidwood Units 1 and 2 reactor facilities. The enclosed report presents the results of that inspection.

During the 6-week period covered by this inspection, your conduct of activities was generally characterized by safety-conscious operations, sound engineering and maintenance practices, and careful radiological work controls.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Sincerely,

A handwritten signature in cursive script, appearing to read "M J Jordan".

Michael J. Jordan, Chief
Reactor Projects Branch 3

Docket Nos. 50-456; 50-457
License Nos. NPF-72; NPF-77

Enclosure: Inspection Report 50-456/99018(DRP);
50-457/99018(DRP)

See Attached Distribution

O. Kingsley

-2-

cc w/encl: D. Helwig, Senior Vice President, Nuclear Services
C. Crane, Senior Vice President, Nuclear Operations
H. Stanley, Vice President, Nuclear Operations
R. Krich, Vice President, Regulatory Services
DCD - Licensing
T. Tulon, Site Vice President
K. Schwartz, Station Manager
T. Simpkin, Regulatory Assurance Supervisor
M. Aguilar, Assistant Attorney General
State Liaison Officer
Chairman, Illinois Commerce Commission