

**From:** David Thompson  
**To:** Shirley Jones  
**Date:** Tue, Jan 11, 2000 7:07 AM  
**Subject:** Re: oconee 99-08

Concur with the security portion.

>>> Shirley Jones 01/10 3:39 PM >>>

Please provide comments/concurrence by 2:00 pm on January 11, 2000.

NOED 99-6-008  
NOED 99-2-004  
EA 98-433

Duke Energy Corporation  
ATTN: Mr. W. R. McCollum  
Vice President  
Oconee Nuclear Station  
7800 Rochester Highway  
Seneca, SC 29672

SUBJECT: NRC INTEGRATED INSPECTION REPORT 50-269/99-08, 50-270/99-08,  
AND 50-287/99-08

Dear Mr. McCollum:

This refers to the inspection conducted from November 7, to December 18, 1999, at your Oconee 1, 2, and 3 reactor facilities. The enclosed report presents the results of this inspection.

During the six-week period covered by this inspection, your conduct of activities at the Oconee facilities was generally characterized by safety conscious operations, maintenance, and engineering practices.

Based on the results of this inspection, the NRC has determined that six violations of NRC requirements occurred. These violations are being treated as Non-Cited Violations (NCVs), consistent with Section VII.B.1 of the Enforcement Policy. These NCVs are described in the subject inspection report. If you contest the violation or severity level of these NCVs, you should provide a response within 30 days of the date of this inspection report, with the basis of your denial, to the United States Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001, with copies to the Regional Administrator, Region II, the Resident Inspectors at the Oconee site, and the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington DC 20555-0001.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and any response, will be placed in the NRC Public Document Room.

Sincerely,

Charles R. Ogle, Chief  
Reactor Projects Branch 1  
Division of Reactor Projects

Docket Nos. 50-269, 50-270, 50-287, 72-04  
License Nos. DPR-38, DPR-47, DPR-55, SNM-2503

Enclosure: Inspection Report 50-269/99-08, 50-270/99-08, 50-287/99-08

cc w/encl: (See page 2)