



DEPARTMENT OF THE NAVY
NAVAL SEA SYSTEMS COMMAND DETACHMENT
RADIOLOGICAL AFFAIRS SUPPORT OFFICE (RASO)
NWS P.O. DRAWER 260
YORKTOWN, VA 23691-0260

ENTER INTO DATABASE _____
FILE: LICENSE: _____
PERMIT: _____
YEARLY: _____
COPY TO PDR _____
OTHER _____

5104/65236
Ser 02B/991468/0768
17 November 1999

From: Officer in Charge, Naval Sea Systems Command Detachment,
Radiological Affairs Support Office (RASO)
To: Commanding Officer, Space and Naval Warfare Systems
Center, Charleston
Subj: RADIOLOGICAL AFFAIRS SUPPORT PROGRAM (RASP) INSPECTION OF
SPACE AND NAVAL WARFARE SYSTEMS CENTER, CHARLESTON ON
15-16 JULY 1999
Ref: (a) CNO ltr 5104 Ser N455C/9U595891 of 23 Aug 99
(b) SPAWARSYSCEN Charleston ltr 9492 Ser 322RS/143 of
22 Sep 99

1. Reference (a) reported deficiencies as a result of the subject inspection of RADIAC calibration operations authorized by Naval Radioactive Materials Permit (NRMP) No. 39-65236-C2NP. Your response to these deficiencies, reference (b), has been reviewed and is considered satisfactory.
2. Corrective actions will be verified during the next inspection of RADIAC calibration operations. This letter serves as final closing action for administrative purposes.
3. NAVSEADET RASO point of contact is Mr. Timothy P. Hart or Mr. Richard W. Lowman at DSN 953-4692, commercial (757) 887-4692 or commercial fax (757) 887-3235.


S. W. DOREMUS

Copy to:
CNO (N455)
COMNAVSEASYS COM (04N/04LR)
NRC Region II
COMSPAWARSYSCOM