

DEPARTMENT OF THE NAVY

NAVAL SEA SYSTEMS COMMAND DETACHMENT RADIOLOGICAL AFFAIRS SUPPORT OFFICE (RASO) NWS P.O. DRAWER 260

YORKTOWN, VA 23691-0260

ENTER INTO DATABASE FILE: LICENSE: PERMIT: YEARLY: COPY TO OTHER

5104/00023 Ser 02B/991493/0775 23 November 1999

From: Officer in Charge, Naval Sea Systems Command Detachment.

Radiological Affairs Support Office (RASO)

To: Commander, Naval Supply Systems Command

Subi: RADIOLOGICAL AFFAIRS SUPPORT PROGRAM (RASP) INSPECTION OF

NAVAL SUPPLY SYSTEMS COMMAND DURING THE PERIOD 21 JUNE

1999 TO 10 AUGUST 1999

Ref: (a) CNO ltr 5104 Ser N455C/9U595892 of 23 Aug 99

(b) NAVSUPSYSCOM ltr 5104 4C3A/255/1 of 21 Sep 99

- Reference (a) reported deficiencies as a result of the subject inspection of radioactive commodities operations authorized by Naval Radioactive Materials Permit (NRMP) No. 37-00023-T1NP. Your response to these deficiencies, reference (b), has been reviewed.
- Compliance with finding I.23 has not yet been achieved. reference (a), progress reports are required every 30 days until all deficiencies are corrected and compliance is achieved. Compliance with all other findings is considered satisfactory.
- NAVSEADET RASO point of contact is Mr. Timothy P. Hart or Mr. Richard W. Lowman at DSN 953-4692, commercial (757) 887-4692 or commercial fax (757) 887-3235.

Copy to: CNO (N455) COMNAVSEASYSCOM (SEA 04N) NRC Region II NAVSUPSYSCOM (4C3A)