

P.O. Box 968 ■ Richland, Washington 99352-0968

January 19, 2000 GO2-00-014

Docket No. 50-397

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Gentlemen:

Subject:

WNP-2, OPERATING LICENSE NPF-21

COMPLETION OF THERMO-LAG 330-1 FIRE BARRIER

CORRECTIVE ACTIONS

References: 1) NRC Generic Letter 92-08, "Thermo-Lag 330-1 Fire Barriers," dated December 17, 1992

2) Letter dated February 17, 1999, SJ Collins (NRC) to JV Parrish (Energy Northwest), "Request for Change to Confirmatory Order Regarding Thermo-Lag 330-1 Fire Barriers for WNP-2 (TAC NO. MA4528)"

Reference 1 required Energy Northwest to confirm in writing when corrective actions that resolved deficiencies in Thermo-Lag fire barrier configurations were completed. Consistent with this requirement, we are informing the staff by this letter that Thermo-Lag fire barrier configuration corrective actions have been completed as of December 31, 1999. Completed corrective actions include physical plant modifications and work package closeout, thereby, ensuring compliance with the Reference 2 confirmatory order to our operating license.

Should you have any questions or desire additional information regarding this issue, please call me or Mr. PJ Inserra at (509) 377-4147.

Respectfully,

DW Coleman

Manager, Regulatory Affairs

Mail Drop PE20

cc: EW Merschoff - NRC RIV

JS Cushing - NRC NRR

NRC Sr. Resident Inspector - 927N

DL Williams - BPA/1399

TC Poindexter - Winston & Strawn

A029