



W3F1-2000-0014 A4.05 PR

February 10, 2000

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Subject:

Waterford 3 SES

Docket No. 50-382 License No. NPF-38

List of High-Risk Motor Operated Valves (MOVs)

## Gentlemen:

On December 14, 1999, during a conference call between Entergy, Waterford 3 Staff and NRC Staff discussing a draft request for additional information (RAI) associated with NRC Generic Letter 96-05, Waterford 3 Staff committed to submit a list of Waterford 3 "high-risk" MOVs. Attached is that list, as determined by our periodic verification test program. The list of risk-significant valves at Waterford 3 is a short list since most of the valves in safety significant applications in the plant are air operated.

This letter contains no new commitments. If you have any questions, please contact O.P. Pipkins at (504) 739-6707.

Very truly yours,

E.P. Perkins, Jr. Acting - Director

**Nuclear Safety Assurance** 

Evenor P. Pacing

reaction carry / locarans

EPP/OPP/rtk Attachment

CC:

E.W. Merschoff (NRC Region IV), N. Kalyanam (NRC-NRR),

J. Smith, N.S. Reynolds, NRC Resident Inspectors Office

## **MOTOR-OPERATED VALVES WITH HIGH RISK-SIGNIFICANCE**

Valve	Description
MS 416	EFW Pump AB Turbine Stop Valve
SI 225A,B	HPSI Header A,B to RC Loop 1A Flow Control Valve
SI 226A,B	HPSI Header A,B to RC Loop 1B Flow Control Valve
SI 227A,B	HPSI Header A,B to RC Loop 2A Flow Control Valve
SI 228A,B	HPSI Header A,B to RC Loop 2B Flow Control Valve
SI 602A,B	Safety Injection Sump Outlet Header A,B Isolation Valve