Mr. Oliver D. Kingsley
President, Nuclear Generation Group
Commonwealth Edison Company
ATTN: Regulatory Services
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT: BRAIDWOOD INSPECTION REPORT 50-456/99019(DRP); 50-457/99019(DRP)

Dear Mr. Kingsley:

On January 25, 2000, the NRC completed an inspection at your Braidwood Units 1 and 2 reactor facilities. The enclosed report presents the results of that inspection.

During the 6-week period covered by this inspection, your conduct of activities was generally characterized by safety-conscious operations, sound engineering and maintenance practices, and careful radiological work controls.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Sincerely.

/s/ M. Jordan Michael J. Jordan, Chief Reactor Projects Branch 3

Docket Nos. 50-456; 50-457 License Nos. NPF-72; NPF-77

Enclosure:

Inspection Report 50-456/99019(DRP);

50-457/99019(DRP)

See Attached Distribution

DOCUMENT NAME: G:BRAI\99019.DRP

To receive a copy of this document, indicate in the box "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No

OFFICE		ERIII ALE	
NAME	Tongue/mt/dp 4	WillJordan 9114V	
DATE	02/9/00	02/9/00 //	

OFFICIAL RECORD COPY

cc w/encl:

D. Helwig, Senior Vice President, Nuclear Services

C. Crane, Senior Vice President, Nuclear Operations

H. Stanley, Vice President, Nuclear Operations R. Krich, Vice President, Regulatory Services

DCD - Licensing

T. Tulon, Site Vice President K. Schwartz. Station Manager

T. Simpkin, Regulatory Assurance Supervisor

M. Aguilar, Assistant Attorney General

State Liaison Officer

Chairman, Illinois Commerce Commission

Distribution:

WES (E-Mail)

GFD (Project Mgr.) (E-Mail)

J. Caldwell, RIII w/encl

B. Clayton, Rill w/encl

SRI Braidwood w/encl

DRP w/encl

DRS wlenci

RIII PRR wlench

PUBLIC IE-01 w/encl

Docket File w/encl

GREENS

IEO (E-Mail)

DOCDESK (E-Mail)



UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 801 WARRENVILLE ROAD LISLE. ILLINOIS 60532-4351

February 09, 2000

Mr. Oliver D. Kingsley
President, Nuclear Generation Group
Commonwealth Edison Company
ATTN: Regulatory Services
Executive Towers West III
1400 Opus Place, Suite 500
Downers Grove, IL 60515

SUBJECT: BRAIDWOOD INSPECTION REPORT 50-456/99019(DRP); 50-457/99019(DRP)

Dear Mr. Kingsley:

On January 25, 2000, the NRC completed an inspection at your Braidwood Units 1 and 2 reactor facilities. The enclosed report presents the results of that inspection.

During the 6-week period covered by this inspection, your conduct of activities was generally characterized by safety-conscious operations, sound engineering and maintenance practices, and careful radiological work controls.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Sincerely,

Michael J. Jordan, Chief Reactor Projects Branch 3

Docket Nos. 50-456; 50-457 License Nos. NPF-72; NPF-77

Enclosure:

Inspection Report 50-456/99019(DRP):

50-457/99019(DRP)

See Attached Distribution

cc w/encl:

D. Helwig, Senior Vice President, Nuclear Services C. Crane, Senior Vice President, Nuclear Operations

H. Stanley, Vice President, Nuclear Operations R. Krich, Vice President, Regulatory Services

DCD - Licensing

T. Tulon, Site Vice President K. Schwartz, Station Manager

T. Simpkin, Regulatory Assurance Supervisor

M. Aguilar, Assistant Attorney General

State Liaison Officer

Chairman, Illinois Commerce Commission