



_2000-052

February 29, 2000

Document Control Desk U. S. Nuclear Regulatory Commission 11555 Rockville Pike Rockville, MD 20852

Attention: C. E. Carpenter

- Subject: Project 704 Transmittal of "BWR Vessel and Internals Project, BWR Core Shroud Inspection and Flaw Evaluation Guidelines (BWRVIP-76NP)," EPRI Report TR-114232NP, January 2000.
- Reference: Letter from C. Terry to C. E. Carpenter, December 15, 1999: Transmittal of "BWR Vessel and Internals Project, BWR Core Shroud Inspection and Flaw Evaluation Guidelines (BWRVIP-76)")," EPRI Report TR-114232, November 1999.

Enclosed are two (2) copies of the report "BWR Vessel and Internals Project, BWR Core Shroud Inspection and Flaw Evaluation Guidelines (BWRVIP-76NP)," EPRI Report TR-114232NP, January 2000. This is the non-proprietary version of the document submitted to the NRC by the letter referenced above.

If you have any questions on this subject please call Steve Lewis of Entergy, BWRVIP Assessment Committee Chairman, at (601) 368-5444.

Sincerely,

Carl Terry Niagara Mohawk Power Company Chairman, BWR Vessel and Internals Project

Enclosure