

Three Mile Island 1
Inspection / Activity Plan
04/02/2000 - 03/31/2001

Units	Inspection Activity	Title	No. of Staff on Site	No. assigned to Procedure	Planned Dates Start	Planned Dates End	Inspection Type
	71130	- SECURITY	2				
1	IP 7113001	Access Authorization Program (Behavior Observation Only)		2	04/10/2000	04/14/2000	Baseline Inspections
1	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and		2	04/10/2000	04/14/2000	Baseline Inspections
	711117B	- PERMANENT MODIFICATIONS	4				
1	IP 7111102	Evaluation of Changes, Tests, or Experiments		4	05/15/2000	05/19/2000	Baseline Inspections
1	IP 711117B	Permanent Plant Modifications		4	05/15/2000	05/19/2000	Baseline Inspections
	71121	- OCCUPATIONAL RAD SAFETY	1				
1	IP 7112101	Access Control to Radiologically Significant Areas		1	07/31/2000	08/04/2000	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		1	07/31/2000	08/04/2000	Baseline Inspections
1	IP 7112103	Radiation Monitoring Instrumentation		1	07/31/2000	08/04/2000	Baseline Inspections
1	IP 71151	Performance Indicator Verification		1	07/31/2000	08/04/2000	Baseline Inspections
	11/6 EXM	- INIT OPER LIC EXAM	2				
1	U01265	THREE MILE ISLAND 1 INITIAL EXAM		2	10/09/2000	10/13/2000	Not Applicable
1	U01265	THREE MILE ISLAND 1 INITIAL EXAM		2	11/06/2000	11/10/2000	Not Applicable
	71114B	- EMERG.PROG.RVW & PI	1				
1	IP 7111402	Alert and Notification System Testing		1	10/16/2000	10/20/2000	Baseline Inspections
1	IP 7111403	Emergency Response Organization Augmentation Testing		1	10/16/2000	10/20/2000	Baseline Inspections
1	IP 7111404	Emergency Action Level and Emergency Plan Changes		1	10/16/2000	10/20/2000	Baseline Inspections
1	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies		1	10/16/2000	10/20/2000	Baseline Inspections
1	IP 71151	Performance Indicator Verification		1	10/16/2000	10/20/2000	Baseline Inspections
	71121	- OCCUPATIONAL RAD SAFETY	1				
1	IP 7112101	Access Control to Radiologically Significant Areas		1	10/30/2000	11/03/2000	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		1	10/30/2000	11/03/2000	Baseline Inspections
1	IP 7112103	Radiation Monitoring Instrumentation		1	10/30/2000	11/03/2000	Baseline Inspections
1	IP 71151	Performance Indicator Verification		1	10/30/2000	11/03/2000	Baseline Inspections
	71152	- PROBLEM IDENTIFICATION & RESOLUTION	4				
1	IP 71152	Identification and Resolution of Problems		2	12/04/2000	12/08/2000	Baseline Inspections
1	IP 71152	Identification and Resolution of Problems		2	12/11/2000	12/15/2000	Baseline Inspections
	71130.03	- SECURITY - RESPONSE	3				
1	IP 7113003	Response to Contingency Events (Protective Strategy and Implementation of Prot		3	12/11/2000	12/15/2000	Baseline Inspections
	711112B	- MAINTENANCE RULE	2				
1	IP 711112B	Maintenance Rule Implementation		2	01/16/2001	01/19/2001	Baseline Inspections
	71121	- OCCUPATIONAL RAD SAFETY	1				
1	IP 7112101	Access Control to Radiologically Significant Areas		1	02/05/2001	02/16/2001	Baseline Inspections
1	IP 7112102	ALARA Planning and Controls		1	02/05/2001	02/16/2001	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

Three Mile Island 1
Inspection / Activity Plan
04/02/2000 - 03/31/2001

Units	Inspection Activity	Title	No. of Staff on Site	No. assigned to Procedure	Planned Dates		Inspection Type
					Start	End	
1	IP 7112103	Radiation Monitoring Instrumentation		1	02/05/2001	02/16/2001	Baseline Inspections
1	IP 71151	Performance Indicator Verification		1	02/05/2001	02/16/2001	Baseline Inspections
	71122.01	- PUBLIC RAD SAFETY - RETS	1				
1	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems		1	03/19/2001	03/23/2001	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.