

BRUNSWICK
Inspection / Activity Plan
04/02/2000 - 03/31/2001

Units	Inspection Activity	Title	No. of Staff on Site	No. assigned to Procedure	Planned Dates Start	Planned Dates End	Inspection Type
	MB-HS	- HEAT SINK	1				
1,2	IP 7111107B	Heat Sink Performance		1	05/22/2000	05/26/2000	Baseline Inspections
	PS-RP	- RADIATION PROTECTION	1				
1,2	IP 7112101	Access Control to Radiologically Significant Areas		1	06/05/2000	06/09/2000	Baseline Inspections
1,2	IP 7112102	ALARA Planning and Controls		1	06/05/2000	06/09/2000	Baseline Inspections
	PS-SEC	- SECURITY	1				
1,2	IP 7113001	Access Authorization Program (Behavior Observation Only)		1	06/26/2000	06/30/2000	Baseline Inspections
1,2	IP 7113002	Access Control (Search of Personnel, Packages, and Vehicles: Identification and		1	06/26/2000	06/30/2000	Baseline Inspections
1,2	IP 71151	Performance Indicator Verification		1	06/26/2000	06/30/2000	Baseline Inspections
	PB4-PI&R	- PROBLEM IDENTIFICATION AND RESOLUTION	3				
1,2	IP 71152	Identification and Resolution of Problems		3	08/28/2000	09/15/2000	Baseline Inspections
	PS-RP	- RADIATION PROTECTION	1				
1,2	IP 7112103	Radiation Monitoring Instrumentation		1	09/11/2000	09/15/2000	Baseline Inspections
	OL EP	- EMERGENCY PREPAREDNESS	2				
1,2	IP 7111401	Exercise Evaluation		2	11/13/2000	11/17/2000	Baseline Inspections
1,2	IP 71151	Performance Indicator Verification		2	11/13/2000	11/17/2000	Baseline Inspections
	PS-RP	- RADIATION PROTECTION	1				
1,2	IP 7112202	Radioactive Material Processing and Transportation		1	01/08/2001	01/12/2001	Baseline Inspections
1,2	IP 71151	Performance Indicator Verification		1	01/08/2001	01/12/2001	Baseline Inspections
	MB-MODS	- PERM PLT MODS & 50.59	3				
1,2	IP 7111102	Evaluation of Changes, Tests, or Experiments		3	02/12/2001	02/16/2001	Baseline Inspections
1,2	IP 711117B	Permanent Plant Modifications		3	02/12/2001	02/16/2001	Baseline Inspections
	PS-RP	- RADIATION PROTECTION	2				
1,2	IP 7112101	Access Control to Radiologically Significant Areas		2	02/12/2001	02/16/2001	Baseline Inspections
1,2	IP 7112102	ALARA Planning and Controls		2	02/12/2001	02/16/2001	Baseline Inspections
1,2	IP 7112202	Radioactive Material Processing and Transportation		2	02/12/2001	02/16/2001	Baseline Inspections
	PS-RP	- RADIATION PROTECTION	1				
1,2	IP 7112101	Access Control to Radiologically Significant Areas		1	02/26/2001	03/02/2001	Baseline Inspections
1,2	IP 7112102	ALARA Planning and Controls		1	02/26/2001	03/02/2001	Baseline Inspections

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.