

---

# NRC INSPECTION MANUAL

---

DIRS

---

Change Notice 11-023

---

## DELETED:

	<u>Number</u>	<u>Date</u>	<u>Number</u>	<u>Date</u>
1.	IMC 1201	06/29/1999	IMC 1201	10/28/11
2.	IMC 0309	02/02/2010	IMC 0309	10/28/11
3.	IMC 0310	02/23/2010	IMC 0310	10/28/11
4.	IMC 2515A	09/03/2008	IMC 2515A	10/28/11

TRAINING: None

REMARKS: IMC 1201, (Conduct of Employees) has been revised and deleted Appendix A and B (redundant and superseded) - provided link and reference to "Summary of Standards of Employee Conduct Regulations 5 CFR 2635". This action resolves FF 1201-1593

IMC 0309, (Reactive Inspection Decision Basis for Reactors) has been revised to add additional deterministic criteria to cover significant operational performance issues where risk assessment tools do not provide reasonable estimates of risk (FF 0309-1650). Added vandalism to the deterministic criteria for security (FF 0309-1414) and expanded the scope of the consideration to events involving safety and security significance for security events (FF 0309-1616).

IMC 0310, (Components With The Cross-Cutting) has been revised definition of Cross Cutting Aspect (FF 0310-1558) and Updated Formatting for improved usability (no red line for formatting changes, FF 0310-1478).

IMC 2515 App A: (Risk-Informed Baseline Inspection Program) IP 71150 was converted into an infrequent procedure in IMC 2515 Appendix C because of the ROP realignment analysis results.

DISTRIBUTION: Standard

END