

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8803080419 DOC. DATE: 88/03/01 NOTARIZED: NO DOCKET #  
 FACIL: 50-000 Generic Docket 05000000  
 50-263 Monticello Nuclear Generating Plant, Northern States 05000263  
 50-282 Prairie Island Nuclear Station, Unit 1, Northern Stat 05000282  
 50-306 Prairie Island Nuclear Station, Unit 2, Northern Stat 05000306  
 AUTH. NAME AUTHOR AFFILIATION  
 RIZVI, S. H. Foxboro Corp.  
 RECIP. NAME RECIPIENT AFFILIATION  
 MAKI, J. R. Northern States Power Co.

SUBJECT: Forwards summary listing of remaining special 62H  
 controllers w/same type of application & resistor valves re  
 resistor value question of remaining controllers.

DISTRIBUTION CODE: IE09D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3  
 TITLE: Vendor-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
INTERNAL:	AEOD/DOA	1 1	AEOD/DSP/ROAB	1 1
	AEOD/DSP/TPAB	1 1	NRR/DLPQ/QAB10A	1 1
	NRR/DRIS/VIB9D4	1 1	NRR/PMAS/ILRB12	1 1
	<del>REG FILE</del> 02	1 1	RGN1/DRP	1 1
	RGN1/DRS	1 1	RGN2/DRP	1 1
	RGN2/DRS	1 1	RGN3/DRP	1 1
	RGN3/DRS	1 1	RGN4/DRSP	1 1
	RGN5/DRSP	1 1		
EXTERNAL:	NRC PDR	1 1		

# The Foxboro Company

Foxboro, MA, U.S.A. 02035  
Telephone 617-543-8750  
Telex 927-602

1 March 1988

Northern States Power Company  
Prairie Island Nuclear Generating Station  
1717 Wakonade Drive East  
Welch, MN 55089

Attention: J.R. Maki, Instrument Engineer

Dear Mr. Maki:


Attached is a summary listing of the remaining special 62H controllers with the same type application and the resistor values.

I believe the attached summary should be satisfactory to resolve the resistor value question of the remaining controllers.

If we may be of any further assistance, please contact us.

Very truly yours,


THE FOXBORO COMPANY



S. Hasan Rizvi, D100/N04-2B  
Manager, Corporate Quality Assurance

pjb  
Attachment

cc: Nuclear Regulatory Commission, Joseph Petrosino



IE:09  
**FOXBORO**

62H CUSTOM INSTRUMENTS

<u>Drawing Number</u>	<u>Change K1 Resistor to</u>	<u>Change K2 Resistor to</u>
WE4470	R89 = 1K	None
WE5014	R89 = 1K	R91 = 2K
WE5015	R89 = 1K	None
WE5114	R89 = 1K	R91 = 2K
WE5178	R89 = 1K	None
WE5309	R43 = 2K	None
WE5429	R89 = 1K	None
WE5430	R89 = 1K	None
WE45759	R43 = 2K	None
WE45866	R43 = 2K	None

Key

1K = N0116PN  
2K = T0124CK

pjb 2/24/88





# The Foxboro Company

Foxboro, MA 02035

**FOXBOBO**

2161 A



United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Attn: Joseph Petrosino  
Washington, DC 20555

