



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
612 EAST LAMAR BLVD, SUITE 400
ARLINGTON, TEXAS 76011-4125

January 17, 2012

MEMORANDUM TO: Duane White, Health Physicist (MS-8F5)
Radioactive Materials Safety Branch
Division of Materials Safety & State Agreements

FROM: Michael Vasquez, Chief */RA Vivian H. Campbell for/*
Nuclear Materials Safety Branch A
Division of Nuclear Materials Safety

SUBJECT: MATERIALS LICENSEE EVENT REPORT SUMMARY

Enclosed is the subject report for November and December, 2011. This enclosure documents the licensee event reports that were closed the preceding month(s), and lists ADAMS ML numbers for documents associated with these events, detailing Region IV's response to these events.

Enclosure:

November and December, 2011 RIV DNMS Licensee
Event Reports Summary Table

cc via email w/Enclosure 1:

- E. Collins
- A. Howell
- R. Caniano
- V. Campbell
- C. Cain
- J. Whitten
- D. Spitzberg
- J. Thompson
- D. Huntsman [Dante.Huntsman@inl.gov]
- LER File

S:\DNMS\INMIB\LERs\2011\11&12-2011.doc

ADAMS	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> SUNSI Review Complete	Reviewer Initials: JLT
	<input checked="" type="checkbox"/> Publicly Available		<input checked="" type="checkbox"/> Non-sensitive	
	<input type="checkbox"/> Non-publicly Available		<input type="checkbox"/> Sensitive	
KEYWORD: SUNSI Review Complete				
RIV:DNMS/NMSB-A		C:NMSB-A		
JLThompson		GMVasquez		
/RA/		/RA VHC for/		
01/09/2012		01/17/2012		

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - DECEMBER 2011

ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status
46450	12/2/2010	12/2/2010	Acuren	42-32443-01	10 CFR 30.50	Sealed source of Ir-192 failed to retract in Prudhoe Bay, Alaska during industrial radiography	Razo	Open
47309	9/30/2011	10/3/2011	United States Air Force	42-23539-01AF	10 CFR 20.2201	Lost americium-241 sealed source (12 millicurie)	Cook	Open
47356	10/19/2011	10/19/2011	Fairbanks Gold Mining	50-29098-01	10 CFR 30.50	Shutter stuck open on fixed nuclear gauge	Poston	Open
ML111920503 ML12012A083	6/22/2011	7/8/2011	Acuren USA	42-32443-01	10 CFR 20.1301	Dose to member of public greater than 2mR in any one hour	Munoz	Closed
ML111510906 ML12012A090	5/25/2011	5/26/2011	National Oceanic & Atmospheric Admin.	46-23463-01	License Condition	Leaking foil source of Nickel-63 in an ECD within gas chromatograph	Hanson	Closed
47263 ML12012A088	9/13/2011	9/13/2011	Queens Medical Center	53-16533-02	10 CFR 35.3045	Medical Event involving the wrong radiopharmaceutical resulting in patient overexposure	Munoz	Closed
ML12004A092	11/10/2011	12/12/2011	Baker Hughes	17-27437-01	10 CFR 39.77	Well logging source abandonment	Thompson	Closed
ML12004A151	11/16/2011	12/20/2011	Baker Hughes	17-27437-01	10 CFR 39.77	Well logging source abandonment	Thompson	Closed
ML11347A188	11/23/2011	12/25/2011	Baker Hughes	17-27437-01	10 CFR 39.77	Well logging source abandonment	Thompson	Closed
46927 ML11304A095	6/4/2011	6/5/2011	ENI US Operating Company	50-29411-01	10 CFR 30.50	Tracerco fixed gauge shutter malfunction	Munoz	Closed
ML11284A119 ML11341A155	5/19/2011	8/31/2011	Department of the Navy	N/A-Reported at Command level	10 CFR 20.2201	Recovery of a previously reported lost generally licensed device	Stearns	Closed