



~~Official Use Only - Security Related Information~~

UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, IL 60532-4352

JAN 04 2012

Robert Turco, Ph.D.
Radiation Safety Officer
The Medical Physics Group, Ltd.
11475 Olde Cabin Road
Suite 200
St. Louis, MO 63141

Dear Dr. Turco:

Enclosed is Amendment No. 09 to your NRC Material License No. 24-24392-01 in accordance with your request. Please note that the changes made to your license are printed in **bold font**.

We could not verify the Capintec sealed source models that you provided. At this time we did not add any Capintec sealed sources per your request to your license.

The estimated exposure dose for Item 5.c. on your letter dated October 6, 2011, was based on the maximum of 4 sources in the tackle box. If the number of sources in the tackle box is more than 4, you should perform ambient radiation survey, evaluate the result and maintain these records in accordance with NRC's rules and regulations.

In addition, we have revised Condition 13.A. on your license to be consistent with our current policy.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate answers and corrections.

You will be periodically inspected by NRC. Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you. This could include issuance of a notice of violation, or imposition of a civil penalty, or an order suspending, modifying or revoking your license as specified in the General Statement of Policy and Procedure for NRC Enforcement Actions. Since serious consequences to employees and the public can result from failure to comply with NRC requirements, prompt and vigorous enforcement action will be taken when dealing with licensees who do not achieve the necessary meticulous attention to detail and the high standard of compliance which NRC expects of its licensees.

The enclosed document contains sensitive security-related information.
When separated from this cover letter this letter is uncontrolled.

~~Official Use Only - Security Related Information~~

R. Turco

~~Official Use Only - Security Related Information~~

2

NRC's Regulatory Issue Summary (RIS) 2005-31 provides criteria to identify security-related sensitive information and guidance for handling and marking of such documents. This ensures that potentially sensitive information is not made publicly available through ADAMS, the NRC's electronic document system. Pursuant to NRC's RIS 2005-31 and in accordance with 10 CFR 2.390, the enclosed license document is exempt from public disclosure because its disclosure to unauthorized individuals could present a security vulnerability. The RIS may be located on the NRC Web site at: <http://www.nrc.gov/reading-rm/doc-collections/gen-comm/reg-issues/2005/ri200531.pdf> and the link for frequently asked questions regarding protection of security related sensitive information may be located at: <http://www.nrc.gov/reading-rm/sensitive-info/faq.html>.

A copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). The NRC's document system is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,



Frank P.D. Tran
Materials Licensing Branch

License No. 24-24392-01
Docket No. 030-18575

Enclosure: Amendment No. 09

The enclosed document contains sensitive security-related information.
When separated from this cover letter this letter is uncontrolled.

~~Official Use Only - Security Related Information~~