

January 25, 2012

MEMORANDUM TO: Patrick L. Hiland, Director
Division of Engineering
Office of Nuclear Reactor Regulation

FROM: David L. Skeen, Director */RA/*
Japan Lessons—Learned Project Directorate
Office of Nuclear Reactor Regulation

SUBJECT: DISPOSITION OF SEISMIC MONITORING ISSUE IDENTIFIED IN
SECY-11-0137

In SECY-11-0137, "Prioritization of Recommended Actions to be Taken in Response to Fukushima Lessons Learned," the staff of the Japan Lessons—Learned Project Directorate identified six additional issues with a clear nexus to the Fukushima Daiichi event that may warrant regulatory action, but which were not included with the Near—Term Task Force recommendations. One of the issues warranting further consideration and potential prioritization is entitled, "Instrumentation for Seismic Monitoring." Senior technical staff completed a preliminary evaluation of this issue and presented the results at the January 10, 2012 meeting of the Japan Lessons—Learned Steering Committee. The Steering Committee decided that this issue should be resolved within the context of the "Action Plan to Address North Anna Power Station Restart As a Result of the August 23, 2011, Earthquake," which also addresses generic issues associated with the August 2011 Central Virginia Earthquake. The Division of Engineering in the Office of Nuclear Reactor Regulation (NRR) has the responsibility to follow-up on any actions necessary as a result of the August 2011, Central Virginia Earthquake and the Division of Operating Reactor Licensing in NRR has the responsibility to track the status of these actions and as such, this issue is no longer being tracked in the Japan Lessons—Learned Process.

CONTACT: Kevin M. Witt, NRR/JLD
301-415-2145

January 25, 2012

MEMORANDUM TO: Patrick L. Hiland, Director
Division of Engineering
Office of Nuclear Reactor Regulation

FROM: David L. Skeen, Director */RA/*
Japan Lessons—Learned Project Directorate
Office of Nuclear Reactor Regulation

SUBJECT: DISPOSITION OF SEISMIC MONITORING ISSUE IDENTIFIED IN
SECY-11-0137

In SECY-11-0137, "Prioritization of Recommended Actions to be Taken in Response to Fukushima Lessons Learned," the staff of the Japan Lessons—Learned Project Directorate identified six additional issues with a clear nexus to the Fukushima Daiichi event that may warrant regulatory action, but which were not included with the Near—Term Task Force recommendations. One of the issues warranting further consideration and potential prioritization is entitled, "Instrumentation for Seismic Monitoring." Senior technical staff completed a preliminary evaluation of this issue and presented the results at the January 10, 2012 meeting of the Japan Lessons—Learned Steering Committee. The Steering Committee decided that this issue should be resolved within the context of the "Action Plan to Address North Anna Power Station Restart As a Result of the August 23, 2011, Earthquake," which also addresses generic issues associated with the August 2011 Central Virginia Earthquake. The Division of Engineering in the Office of Nuclear Reactor Regulation (NRR) has the responsibility to follow-up on any actions necessary as a result of the August 2011, Central Virginia Earthquake and the Division of Operating Reactor Licensing in NRR has the responsibility to track the status of these actions and as such, this issue is no longer being tracked in the Japan Lessons—Learned Process.

CONTACT: Kevin M. Witt, NRR/JLD
301-415-2145

DISTRIBUTION:

JLD R/F	JLD/PSB	JLD/PMB	MVirgilio	ELeeds	MJohnson
RTaylor	NChokshi	CMunson	CCook	MKhanna	AHowe
PHiland	KManoly	MMurphy	YLi	NSalgado	

ADAMS Accession No.: ML12019A259

OFFICE	PM: NRR/JLD/PSB	BC: NRR/JLD/PSB	D: NRR/JLD
NAME	KWitt	MMitchell	DSkeen
DATE	01/19/2012	01/20/2012	01/25/2012

OFFICIAL RECORD COPY