NRC FORM 591M PART 1 (4-2008)			U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION					
1. LICENSEE/LOCATION INSPECTED: Short/Dolan Investments, Inc. dba Pacific Island Inspection 3625 East Ajo Drive Tucson, Arizona 85713 Location: 91270 Hanua Street, Unit #3, Kapolei, Hawaii REPORT NO: 2011-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125		
3. DOCKET NUMBER	2011 001	4. LICENSE NUMBER		5. DATE OF	INSPECTION
030-38103		02-29359-01		Septemb	per 21, 2011
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
4. During this cited. This	inspection certain of you form is a NOTICE OF VI	r activities, as described DLATION, which may be	below and/or attached, were is subject to posting in accorda	in violation of N	IRC requirements and are being R 19.11.
	Linoneno's	Statement of Corr	ective Actions for Iten	n A above	
corrective actions is ma	in 30 days, the actions do	escribed by me to the inserved and control of the inserved and that no further the stand that no further the standard and t	spector will be taken to correct	t the violations ady taken, corr	ective steps which will be taken,
LICENSEE'S REPRESENTATIVE			A A A I I		
NRC INSPECTOR	R. Rick M		Land Muring		09/21/2011
BRANCH CHIEF NRC FORM 591M PART 1 (Re	G. Michael V	asquez	AM Vary X	BRANCH FORMS	1/10/2012 591M FORMS\Pari1 Security Document doc
X Non-Public	X Sensitive – Sec	curity-Related		Public	Non-Sensitive