

February 22, 2012

Ms. Maria K. Rabara, President
Synergy Mobile Imaging, LLC
29488 Woodward Avenue
Suite 284
Royal Oak, MI 48073

SUBJECT: REQUEST FOR RESPONSE TO MULTIPLE ATTEMPTS TO CONTACT YOU
AND CONDUCT AN NRC INSPECTION

Dear Ms. Rabara:

This refers to your License No. 21-32673-01 issued by the Nuclear Regulatory Commission (NRC) that authorizes byproduct material use for diagnostic imaging at temporary job sites. We have attempted to conduct an inspection of your activities authorized at the address referenced above, but have been unable to contact you. Discussions with your consulting physicist, who also serves as your Radiation Safety Officer (RSO), indicated that he could not contact you.

As we described in our email dated February 2, 2012, our office has attempted to conduct an inspection during September 2011, October 2011, and on January 24, 2012. We have visited the authorized storage location listed on your license and found that to be a UPS Store. The UPS Store representative clarified for us that the address on your license may be incorrect because the Suite Number listed in item 2 should actually list a Post Office Box Number. The imaging vehicle could not be located at your authorized location as referenced on your NRC license. We have placed calls to you and left voice mail messages on your personal cellular telephone, however we have not been able to contact you. Although you responded to our February 2, 2012, email informing us that you are no longer in business, our attempts to contact you for additional information and guidance on the licensing process have been unsuccessful.

Please be advised that Title 10 of the Code of Federal Regulations (CFR) Part 19.14 requires that each licensee afford to the Commission the opportunity to inspect materials, activities, facilities, and records related to your NRC license. Please note that the materials possessed under your NRC license must be properly secured in accordance with the terms and conditions

M. Rabara

-2-

of your license. In accordance with 10 CFR 30.36, you may be required to notify the NRC that you have permanently ceased licensed activities. To resolve these matters concerning your license, please contact me at (630) 829-9627 within 10 days from the date of this letter.

Sincerely,

/RA/

Tamara E. Bloomer, Chief
Materials Inspection Branch
Division of Nuclear Materials Safety

cc: V. McCormick, RSO
State of Michigan

M. Rabara

-2-

of your license. In accordance with 10 CFR 30.36, you may be required to notify the NRC that you have permanently ceased licensed activities. To resolve these matters concerning your license, please contact me at (630) 829-9627 within 10 days from the date of this letter.

Sincerely,

/RA/

Tamara E. Bloomer, Chief
Materials Inspection Branch
Division of Nuclear Materials Safety

cc: V. McCormick, RSO
State of Michigan

DISTRIBUTION:

Jennifer Uhle
Anne Boland
Patrick Loudon
Steven Orth
Carole Ariano
Paul Pelke
Patricia Buckley
Tammy Tomczak
MIB Inspectors

ADAMS Accession Number: ML12055A167

DOCUMENT NAME: G:\DNMSIII\Work in progress\LTR- Synergy Mobile Contact.docx

Publicly Available

Non-Publicly Available

Sensitive

Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	RIII DNMS		RIII DNMS		RIII DNMS		RIII	
NAME	DAPiskura: jm DAP		TEBloomer TEB					
DATE	02/22/12		02/22/12					

OFFICIAL RECORD COPY