

[About UL](#)[Businesses](#)[Solutions](#)

Newsroom

[Media Contacts](#)[Press Releases](#)[Public Notices](#)[Story Ideas](#)[UL Press Kit - Background](#)[UL Press Kit - Fact Sheet](#)[Home](#) > [Newsroom](#)

UL Warns of Counterfeit UL Mark on Fire Sprinklers (Release 12PN-05)

NORTHBROOK, Ill., June 15, 2012 - UL is notifying distributors, fire departments, regulatory agencies and authorities having jurisdiction that the Fire Sprinklers identified below bear a counterfeit UL Mark for the United States and Canada. Although the sprinkler frame is marked with the word "TYCO" and the thermo bulb is marked "JOB F5," the sprinkler was not manufactured or labeled by Tyco International, Inc., its affiliates or agents and the thermo bulb was not manufactured by Job, GmbH.

The Fire Sprinklers have not been evaluated by UL to the appropriate Standards for Safety and it is unknown if these Fire Sprinklers comply with the UL safety requirements for the United States or Canada.

Name of Product: Upright and Pendant Fire Sprinklers Model T-ZSTZ-15

Identification: On the product: The counterfeit fire sprinklers can be identified by "UL" and "TYCO" marking on the wrench boss of the fire sprinkler frame and may have model T-ZSTZ-15 on the sprinkler deflector. Sprinklers manufactured by Tyco that are authorized to bear the UL mark do not have "UL" and "TYCO" marking on the wrench boss.

Sold and Distributed By:

Migo International Trading Company Limited
Room 2404, Cell A
No.100 Nanjing Road
Qingdao City, Shandong Province
China

Photographs of the products with counterfeit UL Mark:

Upright:

The following is marked on the fire sprinkler deflector: 2011 T-ZSTZ-15-68°C:



Pendant:

The following is marked on the fire sprinkler deflector: SSP 68°C:



UL is a global independent safety science company offering expertise across five key strategic businesses: Product Safety, Environment, Life & Health, Verification Services and Knowledge Services. Our breadth, established objectivity and proven history mean we are a symbol of trust and enable us to help provide peace of mind to all.

[more](#)

About UL

[History](#)

[Leadership](#)

[Careers](#)

[Newsroom](#)

[Noteworthy](#)

Information for

[Manufacturers](#)

[Code Authorities](#)

[Consumers](#)

[Retailers](#)

Businesses

[Product Safety](#)

[Environment](#)

[Life & Health](#)

[Verification Services](#)

[Knowledge Services](#)

Publications

[The Code Authority](#)

[TCA: Electrical Connections](#)

[Fire & Security Authority](#)

[EPH RegULator](#)

[High-Tech Direct](#)

T
—
M
—
O
—
C
—
U
D
—
S
Li
—
U
—
R
—
H
—
S
—
F,
—

[UL Dialogue](#)

[Lumen Insights](#)

[Contact](#)

[Facebook](#)

[New to UL](#)

[Pinterest](#)

[Twitter](#)

[YouTube](#)

UL and the UL logo are trademarks of UL LLC © 2012 All Rights Reserved. Online Policies.

Newsroom[Media Contacts](#)[Press Releases](#)[Public Notices](#)[Story Ideas](#)[UL Press Kit - Background](#)[UL Press Kit - Fact Sheet](#)[Home](#) > [Newsroom](#)**UL and Loss Prevention Certification Board (LPCB) warn of counterfeit fire sprinkler (Release 12PN-32)**

Northbrook, IL; Watford, UK - July 13, 2012 - UL and the Loss Prevention Certification Board (LPCB) is notifying distributors, contractors, fire departments, regulatory agencies, and authorities having jurisdiction that the Fire Sprinkler identified below bears a counterfeit UL Certification Mark for the United States and Canada and a counterfeit LPCB Mark. The Fire Sprinkler has not been evaluated by UL or LPCB to the appropriate Standards for Safety and it is unknown if the Fire Sprinkler complies with any safety requirements.

Although the sprinkler deflector is marked with model "TY3151" and the thermo bulb is marked "JOB F5" and the wrench boss is marked "GLOBE" the fire sprinkler was not manufactured or labeled by Tyco International, Inc., or Globe Fire Sprinkler Corporation; and the thermo bulb was not manufactured or labeled by Job, GmbH., affiliates or agents.

Note that the counterfeit fire sprinkler is marked with the same model number and constructed similar to a fire sprinkler that is authorized to bear the UL and LPCB Marks. The counterfeit sprinkler is marked "GLOBE" on the wrench boss of the fire sprinkler frame. The fire sprinkler model TY3151 that is authorized to bear the UL and LPCB Marks is not marked "GLOBE".

Name of Product: TY3151

Identification:

On the product: The product bears counterfeit UL and LPC Marks and the following information on the sprinkler deflector: "TY3151 SU 155°F/ 68°C SU" and the wrench boss is marked "GLOBE".

Photographs of the product with counterfeit Marks:



Sold at: Unknown



UL is a global independent safety science company offering expertise across five key strategic businesses: Product Safety, Environment, Life & Health, Verification Services and Knowledge Services. Our breadth, established objectivity and proven history mean we are a symbol of trust and enable us to help provide peace of mind to all.

[more](#)

About UL

[History](#)

[Leadership](#)

[Careers](#)

[Newsroom](#)

[Noteworthy](#)

Information for

[Manufacturers](#)

[Code Authorities](#)

Businesses

[Product Safety](#)

[Environment](#)

[Life & Health](#)

[Verification Services](#)

[Knowledge Services](#)

Publications

[The Code Authority](#)

[TCA: Electrical Connections](#)

Tools

[MyHome](#)

[Online Certifications Directory](#)

[Certification Marks](#)

[UL Collaborative Standards Development System](#)

[Standards Certification Customer Library](#)

[UL iQ™](#)

[Request a Quote](#)

[Consumers](#)

[Fire & Security Authority](#)

[Help](#)

[Retailers](#)

[EPH RegULATOR](#)

[Sitemap](#)

[High-Tech Direct](#)

[FAQs](#)

[UL Dialogue](#)

[Lumen Insights](#)

[Contact](#)

[Facebook](#)

[New to UL](#)

[Pinterest](#)

[Twitter](#)

[YouTube](#)

[About UL](#)[Businesses](#)[Solutions](#)

Newsroom

[Media Contacts](#)[Press Releases](#)[Public Notices](#)[Story Ideas](#)[UL Press Kit - Background](#)[UL Press Kit - Fact Sheet](#)[Home](#) > [Newsroom](#)

UL and Loss Prevention Certification Board (LPCB) warn of counterfeit fire sprinkler (Release 12PN-20)

Northbrook, IL - Watford, UK - April 30, 2012 - UL and the Loss Prevention Certification Board (LPCB) are notifying distributors, contractors, fire departments, regulatory agencies, and authorities having jurisdiction that the Fire Sprinkler identified below bears a counterfeit UL and LPCB certification mark. The Fire Sprinkler has not been evaluated by UL or LPCB to the appropriate Standards for Safety and it is unknown if the fire sprinkler complies with any safety requirements.

Although the sprinkler deflector is marked with GL5661 and the thermo bulb is marked "JOB F5" the sprinkler was not manufactured or labeled by Globe Fire Sprinkler Corporation, and the thermo bulb was not manufactured by Job, GmbH., affiliates or agents.

Note that the counterfeit fire sprinkler is marked with the same model number and constructed similar to a fire sprinkler that is authorized to bear the UL and LPCB Marks. The counterfeit sprinkler is marked "TOP" on the wrench boss of the fire sprinkler frame. Fire sprinkler model GL5661, that is authorized to bear the UL and LPCB Marks, is not marked "TOP."

Name of Product: GL5661

Identification:

On the product: The product bears counterfeit UL and LPC Marks and the following information on the sprinkler deflector: "155°F 68°C SSU-1 2011 GL5661" and the wrench boss is marked "TOP."

Photographs of the product with counterfeit Marks:



Sold at: Unknown



UL is a global independent safety science company offering expertise across five key strategic businesses: Product Safety, Environment, Life & Health, Verification Services and Knowledge Services. Our breadth, established objectivity and proven history mean we are a symbol of trust and enable us to help provide peace of mind to all.

[more](#)

About UL

[History](#)

[Leadership](#)

[Careers](#)

[Newsroom](#)

[Noteworthy](#)

Information for

[Manufacturers](#)

[Code Authorities](#)

[Consumers](#)

[Retailers](#)

UL Dialogue

[Facebook](#)

Businesses

[Product Safety](#)

[Environment](#)

[Life & Health](#)

[Verification Services](#)

[Knowledge Services](#)

Publications

[The Code Authority](#)

[TCA: Electrical Connections](#)

[Fire & Security Authority](#)

[EPH RegULator](#)

[High-Tech Direct](#)

[Lumen Insights](#)

T
M
O
C
U
D
S
L
U
R
H
S
F
C
N

Pinterest

Twitter

YouTube

Copyright 2013 UL LLC. All Rights Reserved. Online Policies.

[About UL](#)[Businesses](#)[Solutions](#)

Newsroom

[Media Contacts](#)[Press Releases](#)[Public Notices](#)[Story Ideas](#)[UL Press Kit - Background](#)[UL Press Kit - Fact Sheet](#)[Home](#) > [Newsroom](#)

UL and Loss Prevention Certification Board (LCPB) warn of unauthorized Marks on fire sprinklers (Release 11PN-45)

Northbrook, IL; Watford, UK - December 5, 2011 -- UL (Underwriters Laboratories) and the Loss Prevention Certification Board (LPCB) are notifying distributors, contractors, regulatory agencies, building owners and authorities having jurisdiction that the fire sprinklers identified below bear unauthorized UL and LPCB Certification Marks. The Fire Sprinklers have not been evaluated by UL or LPCB to the appropriate Standards for Safety and it is unknown if these Fire Sprinklers comply with any safety requirements.

Product: Upright and Sidewall type Fire Sprinklers


Number of Units: Unknown

Manufacturer: Unknown

Date of Manufacture: Unknown

Identification: *On the product:* The product bears an unauthorized UL and LPCB Marks and the word FIREX.

Photographs of the product with unauthorized Marks:



Sold at: Unknown.



UL is a global independent safety science company offering expertise across five key strategic businesses: Product Safety, Environment, Life & Health, Verification Services and Knowledge Services. Our breadth, established objectivity and proven history mean we are a symbol of trust and enable us to help provide peace of mind to all.

more

About UL

History

Leadership

Careers

Newsroom

Noteworthy

Information for

Manufacturers

Code Authorities

Consumers

Retailers

Businesses

Product Safety

Environment

Life & Health

Verification Services

Knowledge Services

Publications

The Code Authority

TCA: Electrical Connections

Fire & Security Authority

EPH RegULator

T
M
O
C
U
D
S
Li
U
R
H
S

[UL Dialogue](#)

[Facebook](#)

[Pinterest](#)

[Twitter](#)

[YouTube](#)

[High-Tech Direct](#)

[Lumen Insights](#)

[FAQs](#)

[Contact](#)

[New to UL](#)
