NRC FORM 591M PART 1 (10-2011)*		U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
I. LICENSEE/LOCATION INSPECTED: Light Sources, Inc. 37 Robinson Boulevard Orange Connecticut REPORT NUMBER(S) 2012-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER	R(S)	5. DATE(S) OF INSPECT	ON
030-38502	06-31445-02E		September 10, 2012	
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Cormission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image:				
Statement of Corrective Actions I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.				
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	Dennis Lawyer		/RA/	9/10/12
BRANCH CHIEF	Judith Joustra		/RA/	9/17/12

*NRC FORM 591M PART 1 (10-2011) (RI Rev. 06/04/2012) Part1.doc G:\WordDocs\Current\Insp Record\06-31445-02E.2012001.591M-

SUNSI Review Completed By:

/ RA / Dennis Lawyer

X Public

X Non-Sensitive