

Anderson, Joseph

From: Anderson, Joseph
Sent: Thursday, June 21, 2012 7:29 AM
To: Bonser, Brian
Cc: Speck, Mark; Berkshire, Douglas; Thaggard, Mark; Norris, Michael; Laughlin, Jeff
Subject: Region II Quarterly Inspection Report Feeders
Attachments: Vogtle Qrtly IR Feeder Memo 02 2012.docx; Brunswick Qrtly IR Feeder Memo 02 2012.docx; Catawba Qrtly IR Feeder Memo 02 2012.docx; Farley Qrtly IR Feeder Memo 02 2012.docx; Hatch Qrtly IR Feeder Memo 02 2012.docx; St. Lucie Qrtly IR Feeder Memo 02 2012.docx

Attached are feeder inputs to the Region II Resident Inspector Quarterly Inspection Reports. These feeder inputs document NSIR staff reviews of the Emergency Plan and Emergency Plan Implementing Procedures that were submitted to the NRC Document Control Desk during the 2nd Quarter CY 2012.

If you have any questions regarding the content of these feeder reports, please contact either Mike Norris (301) 415-4114 or Jeff Laughlin (301) 415-1113.

*Joseph D. Anderson, Chief
Operating Reactor Licensing and Outreach Branch
Division of Preparedness and Response
Office of Nuclear Security and Incident Response
U.S. Nuclear Regulatory Commission*

*Work: (301) 415-4114
Blackberry: (202) 236-6417
Email: joseph.anderson@nrc.gov*

OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE
INPUT TO INTEGRATED REPORT
05000348/2012003 AND 05000364/2012003 FOR
JOSEPH M. FARLEY NUCLEAR PLANT UNITS 1 AND 2

The following is a feeder for integration into the Joseph M. Farley Nuclear Plant Inspection Report Nos. 05000348/2012003 and 05000364/2012003. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 2nd Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR
(301) 415-4098

TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

REPORT DETAILS

1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

a. Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) located under ADAMS accession numbers ML12081A211 and ML12093A204 as listed in the Attachment.

The licensee transmitted the EPIP revisions to the NRC pursuant to the requirements of 10 CFR 50, Appendix E, Section V, "Implementing Procedures." The NRC review was not documented in a safety evaluation report and did not constitute approval of licensee-generated changes; therefore, this revision is subject to future inspection. The specific documents reviewed during this inspection are listed in the Attachment.

b. Findings

No findings were identified.

ATTACHMENT

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee Personnel

N/A

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

NMP-EP-110, "Emergency Classification Determination and Initial Action," Version 3.0

NMP-EP-111, "Emergency Notifications," Version 7.0

NMP-EP-112, "Protective Action Recommendations," Version 2.0

OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE
INPUT TO INTEGRATED REPORT
0500413/2012002 AND 05000414/2012002 FOR
CATAWBA NUCLEAR STATION UNITS 1 AND 2

The following is a feeder for integration into the Catawba Nuclear Station Inspection Report Nos. 05000413/2012002 and 05000414/2012002. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 2nd Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR
(301) 415-4098

TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

REPORT DETAILS

1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

a. Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revision of an Emergency Plan Implementing Procedure (EPIP) located under ADAMS accession number ML12083A135 as listed in the Attachment.

The licensee transmitted the EPIP revision to the NRC pursuant to the requirements of 10 CFR 50, Appendix E, Section V, "Implementing Procedures." The NRC review was not documented in a safety evaluation report and did not constitute approval of licensee-generated changes; therefore, this revision is subject to future inspection. The specific document reviewed during this inspection is listed in the Attachment.

b. Findings

No findings were identified.

ATTACHMENT

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee Personnel

N/A

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

SR/O/B/2000/003, "Activation of the Emergency Operations Facility," Revision 24

OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE
INPUT TO INTEGRATED REPORT
05000325/2012003 AND 05000324/2012003 FOR
BRUNSWICK STEAM ELECTRIC PLANT UNITS 1 AND 2

The following is a feeder for integration into the Brunswick Steam Electric Plant Inspection Report Nos. 05000325/2012003 and 05000324/2012003. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 2nd Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR
(301) 415-4098

TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

REPORT DETAILS

1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

a. Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) located under ADAMS accession number ML12096A029 as listed in the Attachment.

The licensee transmitted the EPIP revisions to the NRC pursuant to the requirements of 10 CFR 50, Appendix E, Section V, "Implementing Procedures." The NRC review was not documented in a safety evaluation report and did not constitute approval of licensee-generated changes; therefore, this revision is subject to future inspection. The specific documents reviewed during this inspection are listed in the Attachment.

b. Findings

No findings were identified.

ATTACHMENT

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee Personnel

N/A

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

OPEP-02.6.21, "Emergency Communicator," Revision 62

OPEP-02.6.27, "Activation and Operation of the Emergency Operations Facility (EOF),"
Revision 30

OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE
INPUT TO INTEGRATED REPORT
05000321/2012003 AND 05000366/2012003 FOR
EDWIN I. HATCH NUCLEAR PLANT UNITS 1 AND 2

The following is a feeder for integration into the Edwin I. Hatch Nuclear Plant Inspection Report Nos. 05000321/2012003 and 05000366/2012003. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 2nd Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR
(301) 415-4098

TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

REPORT DETAILS

1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

a. Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) located under ADAMS accession numbers ML12081A211 and ML12093A204 as listed in the Attachment.

The licensee transmitted the EPIP revisions to the NRC pursuant to the requirements of 10 CFR 50, Appendix E, Section V, "Implementing Procedures." The NRC review was not documented in a safety evaluation report and did not constitute approval of licensee-generated changes; therefore, this revision is subject to future inspection. The specific documents reviewed during this inspection are listed in the Attachment.

b. Findings

No findings were identified.

ATTACHMENT
SUPPLEMENTAL INFORMATION
KEY POINTS OF CONTACT

Licensee Personnel

N/A

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

NMP-EP-110, "Emergency Classification Determination and Initial Action," Version 3.0

NMP-EP-111, "Emergency Notifications," Version 7.0

NMP-EP-112, "Protective Action Recommendations," Version 2.0

OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE
INPUT TO INTEGRATED REPORT
0500335/2012003 AND 05000389/2012003 FOR
ST. LUCIE PLANT UNITS 1 AND 2

The following is a feeder for integration into the St. Lucie Plant Inspection Report Nos. 05000335/2012002 and 05000389/2012003. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 2nd Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR
(301) 415-4098

TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

REPORT DETAILS

1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

a. Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) and the Emergency Plan located under ADAMS accession number ML12089A060 as listed in the Attachment.

The licensee determined that in accordance with 10 CFR 50.54(q), the changes made in the revisions resulted in no reduction in the effectiveness of the Plan, and that the revised Plan continued to meet the requirements of 10 CFR 50.47(b) and Appendix E to 10 CFR Part 50. The NRC review was not documented in a safety evaluation report and did not constitute approval of licensee-generated changes; therefore, this revision is subject to future inspection. The specific documents reviewed during this inspection are listed in the Attachment.

b. Findings

No findings were identified.

ATTACHMENT

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee Personnel

N/A

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

St. Lucie Plant Radiological Emergency Plan, Revision 56
EPIP-01, "Classification of Emergencies," Revision 19

OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE
INPUT TO INTEGRATED REPORT
05000424/2012003 AND 05000425/2012003 FOR
VOGTLE ELECTRIC GENERATING PLANT UNITS 1 AND 2

The following is a feeder for integration into the Vogtle Electric Generating Plant Inspection Report Nos. 05000424/2012003 and 05000425/2012003. This report input documents completion of an Emergency Preparedness Baseline Inspection conducted by NSIR headquarters staff, in accordance with IP 71114.04, "Emergency Action Level and Emergency Plan Changes" during the 2nd Quarter Calendar Year 2012. This input is ready for inclusion into the quarterly integrated resident report and dissemination to the public.

No findings were identified during this inspection.

CONTACT: Michael Norris, NSIR/DPR
(301) 415-4098

TITLE PAGE

Inspector: Jeff Laughlin, Emergency Preparedness Inspector, NSIR

REPORT DETAILS

1. REACTOR SAFETY

Cornerstone: Emergency Preparedness

1EP4 Emergency Action Level and Emergency Plan Changes (IP 71114.04)

a. Inspection Scope

The NSIR headquarters staff performed an in-office review of the latest revisions of various Emergency Plan Implementing Procedures (EPIPs) located under ADAMS accession numbers ML12081A211, ML12093A204, and ML12115A174 as listed in the Attachment.

The licensee transmitted the EPIP revisions to the NRC pursuant to the requirements of 10 CFR 50, Appendix E, Section V, "Implementing Procedures." The NRC review was not documented in a safety evaluation report and did not constitute approval of licensee-generated changes; therefore, this revision is subject to future inspection. The specific documents reviewed during this inspection are listed in the Attachment.

b. Findings

No findings were identified.

ATTACHMENT

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee Personnel

N/A

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

None.

LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

Section 1EP4: .1 Emergency Action Level and Emergency Plan Changes

NMP-EP-110, "Emergency Classification Determination and Initial Action," Version 3.0

NMP-EP-111, "Emergency Notifications," Version 7.0

NMP-EP-112, "Protective Action Recommendations," Version 2.0

91201-C, "Activation and Operation of the Technical Support Center," Revision 17

91202-C, "Activation and Operation of the Operations Support Center," Revision 22