NRC FORM 591M PART 1 (10-2011)* 10 CFR 2.201				
	ETY INSPECTION REPORT		SPECTION	
LICENSEE/LOCATION INSPECTED: Eastern Associated Coal, LLC, Environmental Div. P.O. Box 1233 Charleston, WV 24324-1233		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
REPORT NUMBER(S)	2012001	King of Prussia, Pe	nnsyivania 19406-2	713
 DOCKET NUMBER(S) 030-28938 	4. LICENSE NUMBER 47-24809-01		5. DATE(S) OF INSPECT 08/29/2012	ION
LICENSEE:	47-24009-01		10/29/2012	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X				
I hereby state that, within 30 days, the		Corrective Actions spector will be taken to correct th	e violations identified. Th	is statement of
corrective actions is made in accorda date when full compliance will be ach				
Title	Printed Name	8	Signature	Date
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	R. C. Ragland, Jr.		/RA/	09/20/2012
BRANCH CHIEF	B. D. Welling		/RA/	9/20/2012
*NRC FORM 591M PART 1 (10-2011) (RI Rev. 06/04/2012) G:\WordDocs\Current\Insp Record\R47-24809-01.2012001.591MPart1.docx				
SUNSI Review Completed By:	/ <i>RA</i> / R. C. Ragland,	Jr.	x Public x	Non-Sensitive