



Note: Contours drawn by assumed straight line interpolation between borings and correlation with surface topography. Different conditions may exist between boring locations.

Modified from Cherokee Nuclear Station PSAR Figure 2C-14

WLS COL 2.5-1

<b>WILLIAM STATES LEE III NUCLEAR STATION UNITS 1 &amp; 2</b>	
Top of Rock Contour Map	
FIGURE 2.5.1-227	Rev 0