

Tier / Group	Randomly Selected K/A	Reason for Rejection
1/2 SRO	[295036] 2.4.2	Was unable to write an operationally valid discriminating SRO level question for selected K/A. Randomly selected K/A 2.4.20
1/1 RO	[295037] 2.4.34	This topic was covered in the Audit Exam and is a very narrow topic. Unable to write an additional question for this topic. Randomly selected K/A G 2.4.4
1/2 RO	[295002] AK3.05	Unable to write an RO level question for this K/A. Reason for MSIV isolation on low condenser vacuum is contained in TS Bases. Randomly selected K/A AK3.06
2/1 RO	[209002] K3.01	This topic was covered in the Audit Exam and is a very narrow topic. Unable to write an additional question for this topic. Randomly selected K/A K3.02
2/1 RO	[215005] K3.04	This topic was covered in the previous question and similar sampling in IRM's may lead to oversampling. Unable to write an additional question for this topic. Randomly selected K/A K3.02
2/1 RO	[300000] A3.02	Unable to write an operationally valid question as Instrument Air temperature is not monitored from the Control Room nor do the compressors trip on high air temp. Randomly selected K/A A2.01
3 RO	2.1.8	Question was found unsat during NRC review. Unable to write an operationally valid question at the appropriate level of difficulty. Randomly selected K/A 2.1.41
2/1 SRO	[211000] A2.05	Question was found unsat during NRC review. Unable to write an operationally valid question for this K/A.. Randomly selected K/A A2.04
1/1 RO	[295016] AK3.02	Question was found unsat during NRC review. Unable to write an operationally valid question for this K/A. Randomly selected K/A AK2.02