





FPL

JUN 30 1999

L-99-140
10 CFR 50.55a

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Re: Turkey Point Unit 4
Docket No. 50-251
Inservice Inspection Report

Attached are the following reports for Turkey Point Unit 4 in accordance with the provisions of the ASME Code, Section XI:

Form NIS-1 Owners' Data Report for Inservice Inspections.

Form NIS-2 Owners' Data Report of Repairs and Replacements.

Summary of Visual Examinations and Functional Testing of Snubbers.

Summary of Inservice Inspection Examinations.

Summary of System Pressure Testing.

There were no eddy current examinations scheduled for the Turkey Point Unit 4 steam generators, therefore, Form NIS-BB Owners' Data Report of Eddy Current Examinations Report, is not included.

Should there be any questions concerning this report, please contact us.

Very truly yours,



Don Jennings for

R. J. Hovey
Vice President
Turkey Point Plant

OIH

Attachments

cc: Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9907080066 990630
PDR ADOCK 05000251
G PDR

AD4711

