

B 03/09/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)  
DISTRIBUTION FOR INCOMING MATERIAL

50-296

REC: ORIELLY J P  
NRC

ORG: FOX H S  
TN VALLEY AUTH

DOCDATE: 02/28/78  
DATE RCVD: 03/03/78

DOCTYPE: LETTER NOTARIZED: NO  
SUBJECT:

COPIES RECEIVED  
LTR 1 ENCL 1

LICENSEE EVENT REPT (RD 50-296/78-002) ON 02/14/78 CONCERNING  
BENDIX CONNECTORS OF THE TYPE USED INSIDE THE PRIMARY CONTAINMENT  
HAVE FAILED A POST-AGING ENVIRON TEST AT WYLE LAB TESTING FACILITY.

PLANT NAME: BROWNS FERRY - UNIT 3

REVIEWER INITIAL: XJM  
DISTRIBUTOR INITIAL:

\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*

INCIDENT REPORTS  
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF LEAR\*\*W/4 ENCL

INTERNAL:

REG FILE\*\*W/ENCL  
I & E\*\*W/2 ENCL  
SCHROEDER/IPPOLITO\*\*W/ENCL  
NOVAK/CHECK\*\*W/ENCL  
KNIGHT\*\*W/ENCL  
HANAUER\*\*W/ENCL  
EISENHUT\*\*W/ENCL  
SHAO\*\*W/ENCL  
KREGER/J. COLLINS\*\*W/ENCL  
K SEYFRIT/IE\*\*W/ENCL

NRC PDR\*\*W/ENCL  
MIPC\*\*W/3 ENCL  
HOUSTON\*\*W/ENCL  
GRIMES\*\*W/ENCL  
BUTLER\*\*W/ENCL  
TEDESCO\*\*W/ENCL  
BAER\*\*W/ENCL  
VOLLMER/BUNCH\*\*W/ENCL  
ROSA\*\*W/ENCL

EXTERNAL:

LPDR'S  
ATHENS, AL\*\*W/ENCL  
TIC\*\*W/ENCL  
NSIC\*\*W/ENCL  
ACRS CAT B\*\*W/16 ENCL

DISTRIBUTION: LTR 45 ENCL 45  
SIZE: 1P+1P

CONTROL NBR: 780660019

\*\*\*\*\* THE END \*\*\*\*\*



1950

Faint, illegible text at the top of the page, possibly a header or title.

Second section of faint, illegible text.

Third section of faint, illegible text.

Fourth section of faint, illegible text.

Fifth section of faint, illegible text.

Sixth section of faint, illegible text.

Seventh section of faint, illegible text.

Eighth section of faint, illegible text.

Ninth section of faint, illegible text.

Tenth section of faint, illegible text at the bottom of the page.


TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

REGULATORY DOCKET FILE COPY

FEB 28 1978

Mr. James F. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
230 Peachtree Street, NW., Suite 1217  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 -  
DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE  
OCCURRENCE REPORT BFRO-50-296/782

The enclosed report provides details concerning the Bondix connectors of the type used inside the primary containment which have failed a post-aging environmental test at Wyle Laboratory testing facility. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.a.(9).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox  
Director of Power Production

Enclosure

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

A002  
5  
1/1

FEB 24 1948

THE BOARD OF DIRECTORS  
OF THE NATIONAL ACADEMY OF SCIENCES  
WASHINGTON, D. C.

MEMORANDUM FOR THE BOARD OF DIRECTORS  
SUBJECT: [Illegible]

[Illegible text]

[Illegible text]

THE BOARD OF DIRECTORS

MEMORANDUM FOR THE BOARD OF DIRECTORS  
SUBJECT: [Illegible]

[Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]





Handwritten scribbles in the top right corner.

