

Duke Power Company  
P.O. Box 33198  
Charlotte, N.C. 28242

Hal B. Tucker  
Vice President  
Nuclear Production  
(704)373-4531



**DUKE POWER**

June 18, 1990

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555

Subject: Catawba Nuclear Station, Units 1 and 2  
Docket Nos. 50-413 and 50-414  
NRC Inspection Report Nos. 50-413 and 50-414/90-03  
Revision to Commitment Date

Gentlemen:

In my March 30, 1990 response to Violation 414/90-03-01 concerning failure to take prompt and timely corrective action for the inoperable 2ABFX System, I committed to complete the cleaning of all remaining VA ductwork, susceptible of having lint from dryers, by July 1, 1990.

Vendor personnel assigned this task will be needed to support the current U2EC3 outage and will be unavailable to complete VA ductwork cleaning until late 1990. Based on these outage support needs, I have revised the completion date for VA ductwork cleaning to December 31, 1990.

*Hal B. Tucker*

Hal B. Tucker

WRC140/cs

9006260304 900618  
PDR ADDOCK 05000413  
PDC  
Q

1  
IF01  
110

U. S. Nuclear Regulatory Commission  
June 18, 1990  
Page Two

xc: Mr. Stewart D. Ebnetter  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., NW, Suite 2900  
Atlanta, Georgia 30323

Mr. W. T. Orders  
NRC Resident Inspector  
Catawba Nuclear Station