
James A. FitzPatrick Nuclear Fower Plant P.O. Box 41 Lycoming, New York 13093 315 342-3840



William Fernandez I! Resident Manager

July 16, 1990 JAFP-90-0536

United States Nuclear Regulatory Commission Document Control Desk Mail Station P1-137 Washington, D.C. 20555

SUBJECT: DOCKET NO. 50-333

LICENSEE EVENT REPORT: 89-012-00

Postulated Fault 4KV Bus Fault

Dear Sir:

The referenced LER was submitted on August 11, 1989. At that time, a supplemental report defining long-term corrective action was expected to be submitted on June 30, 1990, approximately six weeks after scheduled completion of the refueling outage. Because the outage was not completed until June 24th, the final determination of long-term corrective action for this LER has been delayed. The supplemental report defining long-term corrective action is now expected to be submitted by September 4, 1990.

Very truly yours,

WILLIAM FERNANDEZ

WF: HCF: lar

cc . LaBarge, USNRC, Region I SNRC Resident Inspector