

## Florida Power

Crystal River Unit 3 Docket No. 50-302

> September 14, 1990 3F0990-05

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, D.C. 20555

Subject:

1990 Inservice Inspection Summary Report

Dear Sir:

Florida Power Corporation (FPC) hereby submits the 1990 Inservice Inspection Summary Report for Crystal River Unit 3. This Summary Report is provided in cordance with the 1983 Edition of the ASME Boiler and Pressure Vessel Code, ion XI. The Report contains the following information:

- o Owner's Data Report for Inservice Inspection (Form NIS-1).
- Data Summary Sections for Class 1, 2 and 3 Components extracted from B&W's report to FPC.
- o Owner's Report for Repairs or Replacements (Form NIS-2).
- o Listing of Examinations.

A summary of Inservice Testing completed by FPC during Refuel 7 is also included for information.

Sincerely,

P.M. Beard, Jr.

Senior Vice President Nuclear Operations

PMB:LVC:wla Attachment

00.

cc: Regional Administrator, Region II Senior Resident Inspector

9009240128 900914 PDR ADOCK 05000302

> POST OFFICE BOX 219 • CRYSTAL RIVER, FLORIDA 32629-0219 • (904) 795-6486 A Florida Progress Company

A047

## 1990 INSERVICE INSPECTION SUMMARY REPORT

## Table of Contents

- Owner's Data Report for Inservice Inspection (Form NIS-1).
- Data Summary Sections for Class 1, 2 and 3 Components extracted from B&W's report to florida Power Corporation (FPC).
- o Ummer's Report for Repairs or Replacements (Form NIS-2).
- o Listing of Ecaminations.