

# SAFEGUARDS INFORMATION

SEP 24 1990

Docket No. 50-302  
License No. DPR-72

Florida Power Corporation  
Mr. Percy M. Beard, Jr.  
Senior Vice President, Nuclear  
Operations  
ATTN: Manager, Nuclear Operations  
Licensing  
P. O. Box 219-NA-21  
Crystal River, FL 32629

SAFEGUARDS INFORMATION REMOVED

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-302/90-25

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by W. Stansberry on August 12-17, 1990. The inspection included a review of activities authorized for your Crystal River facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with 10 CFR 2.790(d) and 10 CFR 73.21, safeguards activities and security measures are exempt from public disclosure. Therefore, the enclosure to this letter with the exception of the report cover page, which presents a nonexempt summary, will not be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

131

William E. Cline, Chief  
Nuclear Materials Safety and  
Safeguards Branch  
Division of Radiation Safety  
and Safeguards

9010020245 900924  
PDR ADDOCK 05000302  
Q FDC

Enclosure:  
NRC Inspection Report  
(Safeguards Information)

cc w/encl: (See page 2)

SAFEGUARDS INFORMATION

TE04  
111  
Document transmitted herewith  
contains sensitive unclassified  
information. When separated from  
enclosures, this document is decontrolled.

SAFEGUARDS INFORMATION

Florida Power Corporation

2

SEP 24 1990

cc w/encl:

Gary L. Boldt  
Vice President, Nuclear Production  
Florida Power Corporation  
P. O. Box 219-SA-2C  
Crystal River, FL 32629

P. F. McKee, Director  
Nuclear Plant Operations  
Florida Power Corporation  
P. O. Box 219-NA-2C  
Crystal River, FL 32629

cc w/Inspection Summary:  
R. C. Widell, Director  
Nuclear Operations Site Support  
Florida Power Corporation  
P. O. Box 219-NA-2I  
Crystal River, FL 32629

A. H. Stephens  
General Counsel  
Florida Power Corporation  
MAC - ASD  
P. O. Box 14042  
St. Petersburg, FL 33723

Attorney General  
Department of Legal Affairs  
The Capitol  
Tallahassee, FL 32304

Jacob Daniel Nash  
Office of Radiation Control  
Department of Health and  
Rehabilitative Services  
1317 Winewood Boulevard  
Tallahassee, FL 32399-0700

Administrator  
Department of Environmental  
Regulation  
Power Plant Siting Section  
State of Florida  
2600 Blair Stone Road  
Tallahassee, FL 32301

(cc w/Inspection Summary cont'd - See page 3)

SAFEGUARDS INFORMATION

Document transmitted herewith  
contains sensitive unclassified  
information. When separated from  
enclosures, this document is decontrolled.

SAFEGUARDS INFORMATION

Florida Power Corporation

3

SEP 24 1990

(cc w/Inspection Summary cont'd)  
State Planning and Development  
Clearinghouse  
Office of Planning and Budgeting  
Executive Office of the Governor  
The Capitol Building  
Tallahassee, FL 32301

Chairman  
Board of County Commissioners  
Citrus County  
110 N. Apopka Avenue  
Iverness, FL 36250

Robert B. Borsum  
Babcock and Wilcox Company  
Nuclear Power Generation Division  
1700 Rockville Pike, Suite 525  
Rockville, MD 20852-1631

State of Florida

bcc w/Inspection Summary:  
Document Control Desk (RIDS IE04), 016  
NRC Resident Inspector

bcc w/encl:  
NRR/DRIS/SB

RII:DRSS  
*WWS*  
WStansberry  
09/21/90

RII:DRSS  
*Emms*  
DMasnyk  
09/24/90

RII:DRSS  
*W*  
DMcGuire  
09/24/90

RII:DRSS  
*R*  
RCrlenjak  
09/24/90

~~RII:DRSS~~  
~~09/24/90~~

SAFEGUARDS INFORMATION

Document transmitted herewith  
contains sensitive unclassified  
information. When separated from  
enclosures, this document is decontrolled.