

DCD/DCB
RIDS

OCT 05 1990

Docket No. 50-456
Docket No. 50-457

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Opus West III
1400 Opus Place - Suite #300
Downers Grove, IL 60515

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. B. L. Jorgensen, J. A. Hopkins, and Ms. D. R. Calhoun of this office from July 29 through September 15, 1990, of activities at the Braidwood Station, Units 1 and 2, authorized by NRC Operating License Nos. NPF-72 and NPF-77, and to the discussion of our findings with Mr. D. E. O'Brien and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

One non-cited violation was identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief
Reactor Projects Branch 1

Enclosure: Inspection Report
No. 50-456/90016(DRP);
No. 50-457/90019(DRP)

See Attached Distribution

0-141

9010170160 901005
PDR ADDCK 05000456
Q PNU

IE01
11

OCT 5 1990

Distribution

cc w/enclosure:
 M. Wallace, Vice President,
 PWR Operations
 T. Kovach, Nuclear
 Licensing Manager
 S. Hunsader, Nuclear
 Licensing Administrator
 K. Kofron, Station Manager
 D. Miller, Regulatory
 Assurance Supervisor
 DCD/DCB (RIDS)
 OC/LFDCB
 Resident Inspectors, Byron,
 Braidwood, Zion
 Richard Hubbard
 J. W. McCaffrey, Chief, Public
 Utilities Division
 Stephen P. Sands, LPM, NRR
 Robert Newmann, Office of Public
 Counsel, State of Illinois Center

RIII
DRC
 CaThoun

RIII
h 10/2
 Landsman

RIII
h 10/2
 ber

RIII
h 10/2
 Greger
 y

RIII
h 10/2
 trafer