



MIDDLE SOUTH
UTILITIES SYSTEM


LOUISIANA
POWER & LIGHT

142 DELARONDE STREET • P.O. BOX 8008
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 388-2345

March 25, 1985

W3P85-0785
Q-3-A35.07
3-A1.01.04
A4.05

Mr. Robert D. Martin
Regional Administrator, Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011



Dear Mr. Martin:

Subject: Waterford 3 SES
Docket No. 50-382
POTENTIALLY REPORTABLE DEFICIENCY NO. 180
"Failure to Maintain Adequate Document Control
of Vendor Manuals"
Extension of Report Schedule

- References:
1. W3P85-0509 from K.W. Cook (LP&L) to R.D. Martin (NRC), dated 2/26/85.
 2. W3P84-2386 from K.W. Cook (LP&L) to J.T. Collins (NRC), dated 9/13/84.

In accordance with 10CFR50.55(e), LP&L provided telephone notification on September 18, 1984 of the subject deficiency. Reference 1 requested an extension for the submittal of a written report on PRD-180 to March 29, 1985. Reference 2 provided LP&L's response to related Violation 8425-01 which specified details on corrective actions planned and underway to resolve this violation.

LP&L requires additional time to evaluate the safety significance of PRD-180 for reportability determination of the deficiency per 10CFR50.55(e) guidance. LP&L has, therefore, rescheduled the submittal of the written report on PRD-180 for April 30, 1985.


85-107
8504090095 850325
PDR ADOCK 05000382
S PDR

IE-27,10

Robert D. Martin
W3P85-0785
Page 2

If you have any questions, please contact Mr. G.E. Wuller (Onsite Licensing Unit Coordinator) at (504) 464-3499.

Very truly yours,



K.W. Cook
Nuclear Support & Licensing Manager

KWC:GEW:DWH:sms

cc: NRC, Director, Office of I&E
G.W. Knighton, NRC-NRR
D.M. Crutchfield, NRC-NRR
NRC Resident Inspectors Office
INPO Records Center (J.T. Wheelock)
E.L. Blake
W.M. Stevenson