



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
December 14, 1984

FILE: B09-13510C
SERIAL: BSEP/84-2725

NRC Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
LICENSEE EVENT REPORT 1-84-32

Gentlemen:

On November 16, 1984, an automatic isolation of the Units 1 and 2 common Control Building Ventilation System occurred due to actuation of the system air intake plenum chlorine detector, 2X-AT-2977, resulting from an erroneous detection of a chlorine alarm condition. The investigation and evaluation of this event is not yet complete. The licensee event report of this event, identified as LER 1-84-32, will be submitted to your office on or before January 4, 1985.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/smp/LETPS1

Enclosure

cc: Mr. R. C. DeYoung
Mr. J. P. O'Reilly

8412270587 841214
PDR ADOCK 05000325
S PDR

IE22
/0