



GLENN L KOESTER VICE PRESIDENT NUCLEAR

December 7, 1984

Mr. R.P. Denise, Director
Wolf Creek Task Force
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Dr. ve, Suite 1000
Arlington, Texas 76011

KMLNRC 84-218

Re: Docket No. STN 50-482

Ref: Interim Report KMLNRC 84-005 dated 01/12/84 from GLKoester, KG&E, to JEGagliardo, NRC

Subj: Final 10CFR50.55(e) Report - Heat Numbers With More Than One Pipe Schedule (53564-K116)

Dear Mr. Denise:

This letter provides the final report submitted pursuant to 10CFR50.55(e) concerning heat numbers with more than one pipe schedule identified at Wolf Creek Generating Station (WCGS). This matter was initially reported on December 13, 1983 with supplemental information provided in the Reference.

As described in the Reference, there were two instances identified in which piping spool pieces of the proper line size but incorrect schedule were installed in piping systems at WCGS. These two piping spool pieces have been replaced with the correct schedule of pipe.

In addition, all actions taken as a result of Correction Action Report (CAR 1-P-0032) have now been completed. These actions included reviews of the heat code cross reference, ultrasonic examination of all installations of the subject heats, as well as personnel training and procedure revisions to prevent any recurrences. No further instances of installed piping spool pieces with the correct heat code and incorrect pipe schedule were identified.

If you have any questions concerning this matter, please contact me or Mr. Otto Maynard of my staff.

Yours very truly,

Slow Lotarte

GLK:bb xc:RCDeYoung PO'Connor (2) HBundy

8501030386 841207 PDR ADOCK 05000482 S PDR

IE-27