NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

JAN 5 1993

Dockets: 50-602 50-192

Licenses: R-129 R-92

Dr. Bernard W. Wehring Nuclear Engineering Teaching Laboratory 10100 Burnet Road The University of Texas at Austin Austin, Texas 78712

SUBJECT: NRC INSPECTION REPORT 50-602/92-02; 50-192/92-02

This refers to the inspection conducted by Mr. L. T. Ricketson of this office on December 7-11, 1992. The inspection included a review of activities authorized for your NRC licenses for the Balcones Research Center and Taylor Hall facilities. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report.

Within the scope of the inspection, no violations or deviations were identified.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 3 of the enclosed report.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely.

67008 .

//L. J. Callan, Director Division of Radiation Safety and Safeguards

EOI 1

DOCUMENT CONTAINS PROPRIETARY INFORMATION DECONTROLLED WHEN SEPARATED FROM ATTACHMENT 2

9301070335 930105 PDR ADOCK 05000192 9 PDR Nuclear Engineering Teaching Laboratory

bcc to DMB w/nonproprietary enclosure only (IEO1)

bcc w/proprietary enclosure: J. L. Milhoan, RA L. J. Callan, DRSS *B. Murray, FIPS *L. T. Ricketson, FIPS *FIPS File *RIV File

bcc w/nonproprietary enclosure:

*DRP *DRS *MIS Coordinator Lisa Shea, RM/ALF (MS 4503) A. Adams, NRR Project Manager (MS 11 B20)

*w/IFS

RIV: FIPS CASS for	C:FIPS	D:DRSS	
LTRicketson:nh	BMurray fo	JCallan	
114193	114/93	1/4/93	

DOCUMENT CONTAINS PROPRIETARY INFORMATION DECONTROLLED WHEN SEPARATED FROM ATTACHMENT 2

Nuclear Engineering Teaching Laboratory

Enclosure: Appendix - NRC Inspection Report 50-602/92-02; 50-192/92-02

cc w/o Proprietary Information: Mr. Tom Bauer Reactor Supervisor Nuclear Engineering Teaching Lab. 10100 Burnet Road The University of Texas at Austin Austin, Texas 78712

Mr. Bill Bryant Radiation Safety Officer Environmental Health and Safety Service Building, Rm. 202 The University of Texas at Austin Austin, Texas 78712-1024

Radiation Control Program Director Bureau of Radiation Control Dept. of Health 1100 W. 49th Street Austin, Texas 78756-3189

Susan Rieff Director of Environmental Policy Office of the Governor P.O. Box 12428 Austin, Texas 78711

DOCUMENT CONTAINS PROPRIETARY INFORMATION DECONTROLLED WHEN SEPARATED FROM ATTACHMENT 2

Nuclear Engineering -3-Teaching Laboratory -3bcc to DMB w/nonproprietary enclosure only (IEO1) bcc w/proprietary enclosure: J. L. Milhoan, RA L. J. Callan, DRSS *B. Murray, FIPS *L. T. Ricketson, FIPS *FIPS File *RIV File bcc w/nonproprietary enclosure: *DRP *DRS *MIS Coordinator Lisa Shea, RM/ALF (MS 4503) A. Adams, NRR Project Manager (MS 11 B20) *w/IFS

RIV: FIPS tos for	C:FIPS	Sto D:DRSS	
LTRicketson:nh	BMurray	ferijCallan	
114-193	114193	1/4/93	

DOCUMENT CONTAINS PROPRIETARY INFORMATION DECONTROLLED WHEN SEPARATED FROM ATTACHMENT 2