



**Northeast
Utilities System**

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128
Waterford, CT 06385-0128
(203) 447-1791

JAN 15 1997

Docket No. 50-336
B16135

Re: 10 CFR 50.73(a)(2)(i)(B)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards supplemental Licensee Event Report (LER) 96-023-01, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on April 25, 1996. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B). This LER supplement provides an update on the analysis and investigation for this event. Additional corrective action based on the results of the investigation are included in this LER.


The following are NNECO's commitments made within this letter. All other statements made within this letter are for information only.

B16135-01: Technical Specification surveillance procedures will be reviewed to ensure compliance with Technical Specification surveillance requirements as part of the Millstone Unit No. 2 Operational Readiness Plan. The review will initially focus on Technical Specification surveillance procedures required for Mode 6 and defueled. Surveillance procedures required for subsequent mode changes will be reviewed prior to mode entry. (This commitment was previously sent to the NRC in the response to NOV 336/96-08-07, NNECO Commitment No. B16076-2.)

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

V. Jerr



J. A. Price

Director - Millstone Unit No. 2

210093

cc: see Page 2

9701220302 970115
PDR ADOCK 05000336
S PDR

Attachment: LER 96-023-01

cc: W. D. Travers, Director of Special Projects
H. J. Miller, Region I Administrator
D. P. Beaulieu, Senior Resident Inspector (Acting), Millstone Unit No. 2
D. G. McDonald, Jr., NRC Project Manager, Millstone Unit No. 2