

Robert W. Boyce Plant Manager Limerick Generating Station

PECO Energy Company Limerick Generating Station PO Box 2300 Sanatoga, PA 19464-0920 610 718 2000

10CFR50.73

January 30, 1997

Locket No. 50-352 License No. NPF-39

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

> SUBJECT: Licensee Event Report Limerick Generating Station - Unit 1

This LER reports a condition prohibited by the Technical Specifications in that the D14 Emergency Diesel Generator Fuel Oil Storage Tank did not contain the minimum amount of fuel oil. The cause of this event was that a challenging method for determining the tank oil level resulted in an operator obtaining an incorrect tank level reading.

Reference: Docket No. 50-352 Report Number: 1-96-022 Revision Number: 00 Event Date: November 2, 1996 Discovery Date: December 31, 1996 January 30, 1997 Report Date: Facility: Limerick Generating Station 1.0. Box 2300, Sanatoga, PA 19464-2300

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(i)(B).

Very truly yours,

Baye

CBN:dbn cc: H. J. Miller, Administrator Region I, USNRC Ferr N. S. Perry, USNRC Senior Resident Inspector, LGS

050007

702050018 970 PDR ADOCK 05000352