



Northeast
Utilities System

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128
Waterford, CT 06385-0128
(203) 447-1791

January 30, 1997
Docket No. 50-336
B16177

Re: 10 CFR 50.73(a)(2)(i)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards Licensee Event Report (LER) 96-043-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on December 31, 1996. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i).

The following are NNECO's commitments made within this letter. All other statements made within this letter are for information only.

B16177-01: Design calibration calculations for QA/Safety Related orifice plates will be verified and a sample of these calculations will be checked to ensure they are consistent with calibration documentation. This will be completed before entry into Mode 4.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

Harry G. Miller as per telecon
for J. A. Price
Director - Millstone Unit No. 2

cc: see page 2

9702050375 970130
PDR ADDCK 05000336
S PDR

IE221

Attachment: LER 96-043-00

cc: W. D. Travers, Director of Special Projects
H. J. Miller, Region I Administrator
D. P. Beaulieu, Senior Resident Inspector (Acting), Millstone Unit No. 2
D. G. McDonald, Jr., NRC Project Manager, Millstone Unit No. 2