



Northeast  
Utilities System

107 Selden Street, Berlin, CT 06037

Northeast Utilities Service Company  
P.O. Box 270  
Hartford, CT 06141-0270  
(860) 665-5000

December 6, 1996

Docket No. 50-423  
B16026

Re:10CFR 50.73(a)(2)(ii)

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Millstone Nuclear Power Station Unit 3  
Licensee Event Report 96-045-00  
Submitted Pursuant to 10CFR 50.73(a)(2)(ii)

This letter forwards Licensee Event Report 96-045-00, documenting a condition that was determined at Millstone Unit No. 3 on November 7, 1996. This LER is submitted pursuant to 10CFR 50.73(a)(2)(ii). NNECO's commitments in response to this event are contained within Attachment 1 to this letter.

Should you have any questions regarding this submittal, please contact Mr. James M. Peschel at (860) 437-5840.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

  
M. H. Brothers  
Unit Director, Millstone Unit No. 3

100004

9612120105 961206  
PDR ADOCK 05000423  
S PDR

IEZZ  
1/1

Attachment: 1) NNECO's commitments in response to LEI 36-045-00  
2) LER 96-045-00

cc: H. J. Miller, Region I Administrator  
A. C. Cerne, Senior Resident Inspector, Millstone Unit No. 3  
V. L. Rooney, NRC Project Manager, Millstone Unit No. 3  
W. D. Travers, Dr., Director, Special Projects

Docket No. 50-423  
B16026

Attachment 1

Millstone Nuclear Power Station, Unit No. 3  
NNECO's Commitments  
In Response To  
(LER 96-045-00)

December 6, 1996

Enclosure  
List of Regulatory Commitments

The following table identifies those actions committed to by NNECO in this document. Any other actions discussed in the submittal represent intended or planned actions by NNECO. They are described to the NRC for the NRC's information and are not regulatory commitments. Please notify the Manager - Nuclear Licensing at the Millstone Nuclear Power Station Unit No. 3 of any questions regarding this document or any associated regulatory commitments.

Number	Commitment	Due
B16026-01	The plant will be revised to conform to the existing design basis, or the design basis will be revised to identify deviations from Regulatory Guide 1.75, Position C.6.	Prior to restart