NOV 27 1985

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Joe Williams, Jr. Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the special safety inspection conducted by Mr. K. D. Ward of this office on August 21-23, September 23-24, and November 12-13 and 25, 1985, of activities at Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. C. Daft at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief Engineering Branch

Enclosure: Inspection Report No. 50-346/85027(DRS)

See Attached Distribution

8512020373 851127 PDR ADOCK 05000346 G PDR

TEO

## Toledo Edison Company

## See Attached Distribution

cc w/enclosure: L. Storz, Plant Manager DCS/RSB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Harold W. Kohn, Ohio EPA James W. Harris, State of Ohio Robert H. Quillin, Ohio Department of Health

Ward/mj 11/22/85 RIII Danielson RIII Burgess Ha7 Harrison