

WOLF CREEK

NUCLEAR OPERATING CORPORATION

Clay C. Warren
Chief Operating Officer

April 30, 1997

WO 97-0049

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-137
Washington, D. C. 20555

- References: 1) Letter ET 97-0044, dated April 23, 1997, from
R. A. Muench to USNRC
2) Letter ET 96-0094, dated November 7, 1996,
from R. A. Muench to USNRC

Subject: Docket No. 50-482: Licensee Event Report 96-010-01

Gentlemen:


The attached Licensee Event Report (LER) revision 96-10-01 is being submitted pursuant to 10 CFR 50.73 (a)(2)(i) concerning a failure to comply with WCGS Technical Specifications.

LER 96-010-00 originally reported the inoperability of Motor Operated Valve EFHV0034 as a violation of Technical Specification 3.7.4. NRC violation 50-482/9704-01 identified that Technical Specification 3.6.3 was entered, but not identified and correctly logged, during the same July 28, 1996 event. Details are contained in the referenced response letter ET 97-0044, and are available on the docket.

During evaluations based on this violation, WCNOG recognized that LER 96-010-00 should have identified this valve inoperability as reportable per Technical Specification 3.6.3, rather than 3.7.4 as originally reported.

If you should have any questions regarding this submittal, please contact me at (316) 364-8831 extension 4485, or Mr. Richard D. Flannigan at extension 4500.

Very truly yours,



Clay C. Warren

CCW/jad

Attachment

cc: E. W. Merschoff (NRC), w/a
W. D. Johnson (NRC), w/a
J. F. Ringwald (NRC), w/a
J. C. Stone (NRC), w/a

9705060393 970430
PDR ADOCK 05000482
S PDR



IE22/1