

#### UNITED STATES

### NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064 MAR 25 1997

Donald F. Schnell, Senior Vice President - Nuclear Union Electric Company P.O. Box 66149 St. Louis, Missouri 63166-6149

SUBJECT: NRC INSPECTION REPORT 50-483/97-03

Dear Mr. Schnell:

Thank you for your letter of March 14, 1997, in response to our letter and Notice of Violation dated February 28, 1997. We have reviewed your reply and find it responsive to the concerns raised in our Notice of Violation. We will review the implementation of your corrective actions during a future inspection to determine that full compliance has been achieved and will be maintained.

Sincerely,

Thomas P. Gwynn, Director Division of Reactor Projects

Docket No.: 50-483 License No.: NPF-30

cc w/enclosure:
Professional Nuclear Consulting, Inc.
19041 Raines Drive
Derwood, Maryland 20855

Gerald Charnoff, Esq.
Thomas A. Baxter, Esq.
Shaw, Pittman, Potts & Trowbridge
2300 N. Street, N.W.
Washington, D.C. 20037

1/1

H. D. Bono, Supervising Engineer Site Licensing Union Electric Company P.O. Box 620 Fulton, Missouri 65251

G. L. Randolph, Vice President Nuclear Operations Union Electric Company P.O. Box 620 Fulton, Missouri 95251

Manager - Electric Department Missouri Public Service Commission 301 W. High P.O. Box 360 Jefferson City, Missouri 65102

Ronald A. Kucera, Deputy Director Department of Natural Resources P.O. Box 176 Jefferson City, Missouri 65102

Otto L. Maynard, President and Chief Executive Officer Wolf Creek Nuclear Operating Corporation P.O. Box 411 Burlington, Kansas 66839

Dan I. Bolef, President
Kay Drey, Representative
Board of Directors Coalition
for the Environment
6267 Delmar Boulevard
University City, Missouri 63130

Lee Fritz, Presiding Commissioner Callaway County Court House 10 East Fifth Street Fulton, Missouri 65151 Alan C. Passwater, Manager Licensing and Fuels Union Electric Company P.O. Box 66149 St. Louis, Missouri 63166-6149

J. V. Laux, Manager Quality Assurance Union Electric Company P.O. Box 620 Fulton, Missouri 65251 bcc to DCD (IEO1)

bcc distrib. by RIV:

Regional Administrator

**DRP** Director

Branch Chief (DRP/B)

Project Engineer (DRP/B)

Branch Cnief (DRP/TSS)

Resident Inspector

DRS-PSB

MIS System

RIV File

Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:\ CW\CW703AK.DGP

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:PE:DRP/B	C:DRP/B	D:DRP N	
SJCampbell;df 42	WDJohnson for	TPGwynn ()	The state of the s
3/25/97	3/25/97 P	3/25/97	

OFFICIAL RECORD COPY

bcc to DCD (IEO1)

bcc distrib. by RIV: Regional Administrator

DRP Director Branch Chief (DRP/B)

Project Engineer (DRP/B)

Branch Chief (DRP/TSS)

Resident Inspector

DRS-PSB

MIS System

RIV File

Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:\ CW\CW703AK.DGP


To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:PE:DRP/B	C:DRP/B	D:DRP 1	J	
SJCampbell;df 452	WDJohnson A	TPGwynn ()	7	
3/25/97	3/25/97 P	365/97	V	

OFFICIAL RECORD COPY



March 14, 1997



Donald F. Schnell Senior Vice President Nuclear

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Stop P1-137 Washington, DC 20555-0001

ULNRC-3546

Gentlemen:

# REPLY TO NOTICE OF VIOLATION INSPECTION REPORT NO. 50-483/97003 CALLAWAY PLANT

This responds to Mr. Arthur T. Howell's letter dated February 28, 1997, which transmitted a Notice of Violation for events discussed in Inspection Report 50-483/97003. Our response to the violation is presented in the attachment.

None of the material in the response is considered proprietary by Union Electric.

If you have any questions regarding this response, or if additional information is required, please let me know.

Very truly yours,

Donald F. Schnell

DFS/tmw

Attachment: 1) Response to Violation

ULNRC-3546 March 14, 1997 Page 2

cc: Mr. James E. Dyer
Regional Administrator - Acting
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-8064

Senior Resident Inspector Callaway Resident Office U.S. Nuclear Regulatory Commission 8201 NRC Road Steedman, MO 65077

Ms. Kristine M. Thomas (2 copies)
Licensing Project Manager, Callaway Plant
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Mail Stop 13E16
Washington, DC 20555-2738

Manager, Electric Department Missouri Public Service Commission PO Box 360 Jefferson City, MO 65102

Mr. Thomas A. Baxter Shaw, Pittman, Potts, & Trowbridge 2300 N. Street N.W. Washington, DC 20037

Manager, Plant Support Wolf Creek Nuclear Operating Corporation PO Box 411 Burlington, KS 66839 Attachment to ULNRC-3546 March 14, 1997 Page 1

### Statement of Violation

During an NRC inspection conducted on January 5 through February 15, 1997, one violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," NUREG-1600, the violation is listed below:

Callaway Plant Technical Specification 6.2.2 f states, in part, that administrative procedures shall be developed and implemented to limit the working hours of unit staff who perform safety-related functions, for example, licensed operators.

Administrative Procedure APA-ZZ-00905, "Limitations of Callaway Plant Staff Working Hours," Revision 3, Step 3.1.1.3, stated that individuals should not be permitted to work more than 24 hours in any 48-hour period. Additionally, Step 3.2 stated that deviations from working hour restrictions shall be approved and documented on Attachment 1, "Request to Exceed NRC Overtime Restrictions," prior to exceeding the overtime restriction.

Contrary to the above, on January 23, 1997, the inspectors identified that two licensed operators exceeded the overtime limits by working greater than 24 hours in a 48-hour period without prior approval and documentation on the "Request to Exceed NRC Overtime Restrictions" form. Specifically:

- On December 4 and 5, 1996, Operator A worked 27.2 hours in a 48-hour period.
- On December 5 and 6, 1996, Operator B worked 26.7 hours in a 48-hour period.

This is a Severity Level IV violation (Supplement I) (50-483/9703-01).

# Reason for the Violation

The violation occurred during a forced outage to repair hydraulic actuator leaks for two main feedwater isolation valves. For both cases, the Superintendent, Operations and the Manager, Callaway Plant were cognizant the licensed operators required authorization to exceed working hour restrictions specified by APA-ZZ-00905. Although Atlachment 1, "Request to Exceed NRC Overtime Restrictions" had not been completed, the working hour restriction deviations had been authorized by the appropriate management specified by APA-ZZ-00905. The reason for the violation was failure to document the authorization.

Attachment to ULNRC-3546 March 14, 1997 Page 2

# Corrective Steps Taken and Results Achieved:

A corrective action document, SOS 97-0098 was initiated on January 23, 1997 to address the concern identified by the NRC resident staff.

## Corrective Steps to Avoid Further Violations:

This violation has been discussed with Operations management personnel. This violation will also be a topic of discussion in meetings conducted by the Superintendent, Operations with Operations department management staff

### Date when Full Compliance will be Achieved:

Full compliance will be achieved by May 1, 1997.