

CP&L

Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429

May 11, 1988

FILE: B09-13510C
SERIAL: BSEP/88-0474

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555


BRUNSWICK STEAM ELECTRIC PLANT UNITS 1 AND 2
DOCKET NOS. 50-325 AND 50-324
LICENSE NOS. DPR-71 AND DPR-62
SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.7.2 AND
PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (1-SR-88-001)

Gentlemen:

During Unit 1 power operation concurrent with the Unit 2 1988 refueling/maintenance outage, a limiting condition for operation (LCO) was established on April 5, 1988, for fire protection deluge valve 1-FP-DV-22 to the sprinkler system of the units' common Service Water Building. This was done to permit isolation of the valve for repair of a leak involving the valve clapper latch seat ring. Due to a temporary unavailability of qualified replacement parts, the specified 14-day time frame of the LCO was exceeded on April 19, 1988.

Until completion of the required repairs and return of the valve to service, the subject LCO, with appropriate fire watches and backup fire suppression equipment, will remain in effect.

Very truly yours,



C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/srg

Enclosure

cc: Dr. J. N. Grace
Mr. E. D. Sylvester
BSEP NRC Resident Office